

N1598 LEFT



PROPELLER SERVICE, INC.

Propeller Logbooks
1-800-334-6437

FAA-711-8

PROPELLER MAINTENANCE RECORD

LEFT ENGINE

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. Nos. _____

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____

RIGHT ENGINE

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. Nos. _____

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
10 May 95		Overhauled (1) propeller s/n HC-E24R-2RBSF s/n BP8265, c/w S.B. 118D, 136H, 150, 151A, 255, 164C, S.L. 61R, 82A, 148A, 154, S.I. 117, and balanced under	

SERVICEABLE PART

MANUFACTURER *Hentzell*
 PART NAME *Propellers*
 MODEL *HC-E24R-2RBSF*
 PART NO. _____
 SERIAL NO. *BP8265*
 REMARKS *Overhauled, s/n's T. 118D, 136H, 150,
151A, 155, 148C, S.L. 61R, 82A, 148A, 154,
S.I. 117, 119, 170, s/n's not provided
and balanced. Bldg Dist # F1167.72
#1) D38408 #2) D38387*

ACCOMPLISHED BY *John Gray*

THE AIRCRAFT PROPELLER, OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER:

Order No. *59489* Date *10 May 95*
 Signed *John Gray*
 Signature of Authorized Representative

FOR
H & H PROPELLER SERVICE
 Burlington Municipal Airport
 Burlington, NC 27215

F.A.A. REPAIR STATION NO. PS41451M

colp

SERVICEABLE PART

MANUFACTURER

PART NAME

QTY

DATE

BY

REMARKS

Manufacturer: Hamilton
Part Name: Propeller
QTY: 1
DATE: 12-16-88
BY: RBST

REMARKS: 31325
Dedicated propeller
CWS 1.1188

Inspected by: Steve Yang

THIS PART HAS BEEN INSPECTED AND FOUND TO BE IN AIRWORTHY CONDITION. THE PART IS IDENTIFIED BY THE PART NAME AND QTY. THE PART IS IDENTIFIED BY THE PART NAME AND QTY.

INSPECTION IS LIMITED TO THE PART IDENTIFIED BY THE PART NAME AND QTY.

IF THE PART IS FOUND TO BE IN UNAIRWORTHY CONDITION, THE PART SHOULD BE REJECTED.

IF THE PART IS FOUND TO BE IN AIRWORTHY CONDITION, THE PART SHOULD BE ACCEPTED.

Signed: [Signature]

Date: 12/16/88

FAH PROPELLER SERVICE

Garfield Municipal Airport

Garfield, NJ 07824

609-885-2344

SIGNATURE

Inspected on: APER

FAH Prop

PROP. ANTHONY D. CASEY

A&P 251967817

[Signature]

A ANNUAL

INSPECTION AND WAS

(84) 574-8560

DETERMINED TO BE IN AIRWORTHY CONDITION

ANTHONY D. CASEY

A&P 251967817 SA

[Signature]

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
MAR 18 1999	H.M 1709.3	Propeller REINSTALLED IN #1 (Left) position on Piper	
		Aztec N1598 SN 27-7754047. INSTALLATION PERFORMED EXW P/P	
		Service Manual PN 753 564. GREASED AND SERVICED prop. ANTHONY D. CASEY	
DATE <u>MAR 18 1999</u>	TOTAL TIME <u>795.9 smoh</u>	TACH. <u>1709.3</u>	A&P 251967817 <i>Anthony D. Casey</i>
I CERTIFY THAT THIS <u>Propeller</u> HAS BEEN INSPECTED IN ACCORDANCE WITH			CITY OF SPARTANBURG SPARTANBURG DOWNTOWN AIRPORT 500 AMMONS ROAD SPARTANBURG, SC 29306 (804) 574-8560
A <u>Annual</u> INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION ANTHONY D. CASEY			A&P 251967817 SA
<i>Anthony D. Casey</i>			

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	DATE	TACH TIME	DESCRIPTION OF WORK	TACH TIME	SIGNATURE
SEP 02 2003	DEC 05 2004				
TOTAL TIME <u>1280.7</u>	TOTAL TIME <u>1331.8</u>	TACH. <u>2214.1</u>	TACH. <u>2265.2</u>		
I CERTIFY THAT THIS <u>Propeller</u>	I CERTIFY THAT THIS <u>Propeller</u>				
HAS BEEN INSPECTED IN ACCORDANCE WITH	HAS BEEN INSPECTED IN ACCORDANCE WITH				
A <u>Special</u> INSPECTION AND WAS	A <u>Special</u> INSPECTION AND WAS				
DETERMINED TO BE IN AIRWORTHY CONDITION	DETERMINED TO BE IN AIRWORTHY CONDITION				
SIGNATURE <u>[Signature]</u>	SIGNATURE <u>[Signature]</u>				
CERTIFICATION NO. <u>PA 1281967817 EA</u>	CERTIFICATION NO. <u>A 1237782541 IA</u>				

H & H PROPELLER SERVICE, INC.
 2300 BOOTH AVENUE DRIVE
 DUNSTON, MARYLAND 21046
 TEL: 410-326-1212
 FAX: 410-326-1211

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
01/16/2006	H.P. 2307.4 TSMOH 1374.0	THIS Propeller has been removed from N159B Due to loose item in nose dome	Anthony D. Casey

SERVICEABLE PART



MANUFACTURER: Hartnell
 PART NAME: Propeller
 MODEL: F2412-DR05
 PART NO.: BP 8065
 SERIAL NO.: Repaired dome

ACCOMPLISHED BY: Steve Young
 THE AIRCRAFT PROPELLER OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE.
 PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER:

Order No. 14936 Date 1/16/06
 Signature: Steve Young
Signature of Authorized Representative

H & H PROPELLER SERVICE
 Burlington Municipal Airport
 Burlington, NC 27215

F.A.A. REPAIR STATION NO.: PS4R453M

WIFE



**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
01/16/2006	H.W. 2307.4 TSMOH 1374.0	THIS Propeller has been removed from NISS B Due to base item in nose dome.	ANTHONY D. CASSEY RAE 25196 WIFE <i>[Signature]</i>
23 Jan 06		Repaired dome on propeller m/w HC-E2YR-2RBSF s/n BP 8265 by H & H Propeller Service w/prop washer. WO# 14336.	<i>[Signature]</i>
		H & H PROPELLER SERVICE, INC. 3439 SOUTH AVIATION DRIVE BURLINGTON MUNICIPAL AIRPORT BURLINGTON, N. C. 27215 FAA REPAIR STATION PS4R451M 1-800-334-6437	

