

N1598 LEFT



PROPELLER SERVICE, INC.

Propeller Logbooks
1-800-334-6437

FAA-711-8

PROPELLER MAINTENANCE RECORD

LEFT ENGINE

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. Nos. _____

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____

RIGHT ENGINE

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. Nos. _____

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
10 May 95		Overhauled (1) propeller s/n HC-E24R-2RBSF s/n BP8265, c/w S.B. 118D, 136H, 150, 151A, 255, 164C, S.L. 61R, 82A, 148A, 154, S.I. 117, and balanced	

SERVICEABLE PART

MANUFACTURER *Hentzell*
 PART NAME *Propeller*
 MODEL *HC-E24R-2RBSF*
 PART NO. _____
 SERIAL NO. *BP8265*
 REMARKS *Overhauled, s/n's T. 118D, 136H, 150,
151A, 155, 148, S.L. 61R, 82A, 148A, 154,
S.I. 117, 119, 170, s/n's ed, s/n's ed
and balanced. Bldg Dist # F1167.72
#1) D38408 A-2) D38387*

ACCOMPLISHED BY *John Gray*

THE AIRCRAFT PROPELLER, OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER:

Order No. *59489* Date *10 May 95*
 Signed *John Gray*
 Signature of Authorized Representative

FOR: **H & H PROPELLER SERVICE**
 Burlington Municipal Airport
 Burlington, NC 27215

F.A.A. REPAIR STATION NO. PS41451M

and balanced under

colp

SERVICEABLE PART

MANUFACTURER

PART NAME

QTY

DATE

BY

REMARKS

Hamilton
Propeller
A/C - 6-1/2" - ARBF

3/13/25
Rechecked propeller
OK

Inspected by Steve Yang

THIS PART HAS BEEN INSPECTED BY A QUALIFIED PERSON AND FOUND TO BE IN AIRWORTHY CONDITION. THE PERSON WHO INSPECTED THIS PART IS RESPONSIBLE FOR THE ACCURACY OF THE INFORMATION CONTAINED HEREIN.

THIS PART IS TO BE USED IN ACCORDANCE WITH THE INSTRUCTIONS CONTAINED IN THE AIRCRAFT MAINTENANCE MANUAL.

DATE OF INSPECTION

SIGNED

NAME

3/13/25
Steve Yang

FAH PROMELLER SERVICE

Garfield Municipal Airport

Garfield, NJ 07824

FAH PROMELLER SERVICE

SIGNATURE

Inspected on APER

on FAA Form

PROP. ANTHONY D. CASEY

A&P 251967817

Anthony D. Casey

A ANNUAL

INSPECTION AND WAS

(84) 574-8560

DETERMINED TO BE IN AIRWORTHY CONDITION

ANTHONY D. CASEY

A&P 251967817 SA

Anthony D. Casey

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
MAR 18 1999	H.M 1709.3	Propeller REINSTALLED IN #1 (Left) position on Piper	
		Aztec N1598 SN 27-7754047. INSTALLATION PERFORMED EXW P/P	
		Service Manual PN 753 564. GREASED AND SERVICED prop. ANTHONY D. CASEY	
DATE MAR 18 1999	TOTAL TIME 795.9 smoh TACH. 1709.3	CITY OF SPARTANBURG	A&P 251967817 SA Anthony D. Casey
I CERTIFY THAT THIS Propeller	HAS BEEN INSPECTED IN ACCORDANCE WITH	SPARTANBURG DOWNTOWN AIRPORT	
A Annual	INSPECTION AND WAS	500 AMMONS ROAD	
ANTHONY D. CASEY	DETERMINED TO BE IN AIRWORTHY CONDITION	SPARTANBURG, SC 29306	
	A&P 251967817 SA	(844) 574-8560	

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	DATE	TACH TIME	DESCRIPTION OF WORK	TACH TIME	SIGNATURE
SEP 02 2003	DEC 05 2004				
TOTAL TIME <u>1280.7</u>	TOTAL TIME <u>1331.8</u>	TACH. <u>2214.1</u>	TACH. <u>2265.2</u>		
I CERTIFY THAT THIS <u>Propeller</u>	I CERTIFY THAT THIS <u>Propeller</u>				
HAS BEEN INSPECTED IN ACCORDANCE WITH	HAS BEEN INSPECTED IN ACCORDANCE WITH				
A <u>Special</u> INSPECTION AND WAS	A <u>Special</u> INSPECTION AND WAS				
DETERMINED TO BE IN AIRWORTHY CONDITION	DETERMINED TO BE IN AIRWORTHY CONDITION				
SIGNATURE <u>[Signature]</u>	SIGNATURE <u>[Signature]</u>				
CERTIFICATION NO. <u>PA 1281967817 EA</u>	CERTIFICATION NO. <u>A 1237782541 IA</u>				

H & H PROPELLER SERVICE, INC.
 2300 BOOTH AVENUE DRIVE
 DUNSTON, MARYLAND 20754
 1-800-334-6137

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
01/16/2006	A.P. 2307.4	TSMOH 1374.0 THIS Propeller has been removed from N159B Due to loose item in nose dome	Anthony D. Ensey

SERVICEABLE PART

MANUFACTURER: Hartnell
 PART NAME: Propeller
 MODEL: FA12 - DR08
 PART NO.: BP 2065
 SERIAL NO.:
 REMARKS: Repaired dome

ACCOMPLISHED BY: Steve Young
 THE AIRCRAFT PROPELLER OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER:

Order No. 14936 Date 1/16/06
 Signature: Problem Joe Crop
Signature of Authorized Representative

H & H PROPELLER SERVICE
 Burlington Municipal Airport
 Burlington, NC 27215

F.A.A. REPAIR STATION NO.: PS4R453M

WIFE
Phy
Judge
Joe Crop

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
01/16/2006	H.W. 2307.4 TSMOH 1374.0	THIS Propeller has been removed from NISS B Due to base item in nose dome.	ANTHONY D. CASSEY RAE 25196 WIFE <i>[Signature]</i>
23 Jan 06		Repaired dome on propeller m/w HC-E2YR-2RBSF s/n BP 8265 by H & H Propeller Service w/prop washer. WO# 14336.	<i>[Signature]</i>
		H & H PROPELLER SERVICE, INC. 3439 SOUTH AVIATION DRIVE BURLINGTON MUNICIPAL AIRPORT BURLINGTON, N. C. 27215 FAA REPAIR STATION PS4R451M 1-800-334-6437	

