



The Standard

PROPELLER LOG

MSA-SPL



The Standard

PROPELLER LOG

ASA-SP-L

Propeller Record General Information

Propeller Manufacturer MCCavley Ind. Corp
Model 1A170 FF7563 s/n P79766 Type _____
Hub Series # _____ Blade # _____

Date of Manufacture _____

Prop Installed new at Tach 374
20 Dec 1978.

Aircraft Installed On: Grumman/AA-5B Make/Model AA5B-0019 Serial #

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: _____
 Date: _____
 Next Inspec Due: _____

St. Charles Flying Service, Inc
 6016 Portage Road Portage De Sioux MO 63373(1-800-447-6066)

N1519R Date: 06-4-2015 Tach: 2713.4 TTP: 2339.4
 Engine ~~Model: O-360-A4K~~ S/N: L-19630-36A
 Prop

- Year: _____
 Date: _____
1. Removed spinner, inspected prop and bulkheads.
 2. Reinstalled spinner.
 3. Dressed blades.

I certify this propeller has been inspected in accordance with a manufacturers 100hr and was determined to be in safe condition for flight.


 Jeff Lucchesi A&P3572218

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
Mech. Cert. # or Repair Station # _____		

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS



Aircraft Maintenance Specialties, Inc.

Year: _____
Date: _____
Next Inspection Due: _____

January 13, 2016

N1519R

Tach: 2715.7

Hobbs:

PTSN: 2341.7

Removed propeller and Re-installed after paint. With respect to the work performed, this propeller is approved for returned to service. Details of work performed are on file with Aircraft Maintenance Specialties, Inc. under work order: AMS2897.

Kent Lischer

A&P IA

3434937

Kent D. Lischer

Year: _____
Date: _____
Next Inspection Due: _____

in Service

Time Since Overhaul

Mech. Cert. # or Repair Station # _____


WESTERN PLAINS AVIATION LLC 3401 E 8TH STREET GREELEY, CO 80634 (970)-373-4550
 LOG ID# 277 11-July-2016 WO# 143/3 WPAF007.0 AC TT 2729.5
 N1519R S/N AA5B-0019 GRUMMAN AA-5B
 SPOH 2355.5

Pg 1 / 1

**** ITEM # 143-3 Annual propeller ****

DISCREPANCY: Annual propeller

ACTION: I certify that this propeller has been inspected in accordance with an annual inspection, and was determined to be in airworthy condition. AD's researched through bi-weekly 2016/14 .


 Signed 2627467A&PIA Steve McIntire

7/11/2016
 Date

	Time Since Overhaul	Mech. Cert. # or Repair Station # _____
Year: _____	Total Time in Service	Description
Date: _____		
Next inspection Due: _____	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

WESTERN PLAINS AVIATION LLC 3401 E 8TH STREET GREELEY, CO 80634 (970)-373-4550
 LOG ID# 278 13-July-2016 WO# 143/4 WPAF007.0 AC TT 2729.5
 N1519R S/N AA5B-0019 GRUMMAN AA-5B
 SPOH 2355.5

Pg 1 / 1

**** ITEM # 143-4 Spinner/bck plt/blk head damage ****
 DISCREPANCY: Spinner/bck plt/blk head damage
 Part#: 5506008-505
 ACTION: R&R Spinner, bulkhead, backplate, doubler, screws, and washers. Installed propeller and torqued bolts to 63ft/lb, safetyed bolts with .040 safety wire. Operated engine with no defects observed. P/N 5506009-3, 5506010-503, 5506011-3, 5506008-505.

Signed  Larry Roberts

Date

July 13th 2016

Year:	Total Time in Service	Description
Date:		
Next Inspection Due:	Time Since Overhaul	Mech. Cert. # or Repair Station #

(Continuous History of Changes in Structure or Equipment Affecting Weight and Balance)

AIRPLANE MODEL <i>American Brewster Tiger AA5B</i>		SERIAL NUMBER <i>0019</i>		<i>N1519R</i>	
Gross Weight	<i>2400.00</i>	Empty Weight	<i>1427.65</i>	Useful Load	<i>972.35</i>
				<i>973.15</i>	

DATE	DESCRIPTION OF ARTICLE OR MODIFICATION	WEIGHT CHANGE						EMPTY WEIGHT	
		ADDED (+)			REMOVED (-)			Wt. (lb.)	Moment /1000
		Wt. (lb.)	Arm (In.)	Moment /1000	Wt. (lb.)	Arm (In.)	Moment /1000		
<i>3/16/01</i>	<i>Removed Picstlite starter, installed skytak starter part # 31A22104 Model 149-12LS</i>							<i>1427.65</i>	<i>120449</i>
<i>1/19/09</i>	<i>Removed Neco Com IIA S/N 106234720 F2L68012 Installed TKMx11 SW</i>	<i>2.6</i>	<i>62.16</i>	<i>161.61</i>	<i>3.2</i>	<i>62.16</i>	<i>198.9</i>	<i>-6</i>	<i>-37.2</i>
<i>1/19/09</i>	<i>Removed Apoll # LORAN SW 34684 Installed Garmin 496 GPSMAP SW 19720553</i>	<i>1.9</i>	<i>62.38</i>	<i>118.52</i>	<i>2.4</i>	<i>62.38</i>	<i>149.71</i>	<i>-5</i>	<i>-31.1</i>
								<i>1427.65</i>	<i>120412</i>
								<i>-5</i>	<i>-31.1</i>
								<i>1426.55</i>	<i>120381</i>

