


RIGHT



PROPELLER SERVICE, INC.

Propeller Logbook
1-800-334-6437

FAA-711-8



PROPELLER MAINTENANCE RECORD

LEFT ENGINE

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. Nos. _____

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____

RIGHT ENGINE

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. Nos. _____

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
10 May 95		Overhauled (1) propeller on/w HC-E24R-2RBSF s/n BP 8278 c/w S.B. N8D 136H, 150, 151A, 155, 169C, S.L. 61R, 82A, 128H, 154 S.F. 117, 144, 152, 170 ground painted and balanced. Bal. Data # F3465.20 T1) B4107 # 3DP46632	

SERVICEABLE PART

MANUFACTURER *Hartzell*
 PART NAME *Propeller*
 MODEL *HC-E24R-2RBSF*
 PART NO. _____
 SERIAL NO. *BP 8278*
 REMARKS *Overhauled (1) w S.B. N8D,
136A, 150, 151A, 155, 169C, S.L.
61R, 82A, 128H, 154 S.F. 117,
144, 152, 170 ground painted
and balanced. Bal. Data # F3465.20
T1) B4107 # 3DP46632*

ACCOMPLISHED BY *Yoo Chup*

THE AIRCRAFT PROPPELLER OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE.

PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER:

Order No. *6489* Date *11 May 95*
 Signed *Yoo Chup* Signature of Authorized Representative

FOI: **H & H PROPELLER SERVICE**
 Burlington Municipal Airport
 Burlington, NC 22215

F.A.A. REPAIR STATION NO. P54645JM

*and balanced
under*

Yoo Chup

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
10 May 95		<p>Overhauled (1) propeller on/n HC-E24R-2RB3F s/n BP 8278 C/W S.B. 118D, 136H, 150, 151A, 155, 164C S.L. 61R, 82A, 148A, 154 S.F. 117, 144, 152, 170, greased, painted, and balanced by H & H Propeller Service Inc under DDO# 6489.</p> <p>H & H PROPELLER SERVICE INC. 3532 AIRPORT LOOP ROAD BURLINGTON MUNICIPAL AIRPORT BURLINGTON, N. C. 27215 FAA REPAIR STATION PS4R451M 1-800-334-6437</p>	<p><i>Yvette Garcia</i></p>

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
MAY 10	1445 TBM 153.4	INSTALL Prop 252001 N 1778. Run up & check for leaks. Anthony D. Casey	Shelby Aviation P. O. Box 1221 Municipal Airport Shelby, N. C. 28150
		144751-467117 <i>Anthony D. Casey</i>	
OCT 29 1988	H.M 1709.3	Removed prep for tree sludge	Anthony D. Casey 144751967817 <i>Anthony D. Casey</i>
	CITY OF SPARTANBURG SPARTANBURG DOWNTOWN AIRPORT 510 ANTHONY'S ROAD SPARTANBURG, SC 29306 (64) 574-5360		

SERVICEABLE PART

MANUFACTURER Hartzel
 PART NAME Propeller
 MODEL HC-EZYK DR 25F
 PART NO. _____

SERIAL NO. BP8318

REMARKS Inspected propeller
 W.S.T. H.P.

ACCOMPLISHED BY Steve Bacon

THE AIRCRAFT PROPELLER OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER _____

Order No. 9037 Date 18 Jan 99

Signed [Signature] Captain or Authorized Representative

H & H PROPELLER SERVICE

Burlington Municipal Airport
 Burlington, NC 27215

F.A.A. REPAIR STATION NO. P53634MM

SIGNATURE

W Piper Aztec
performed work
serviced prop.

AIRPORT

DATE MAR 18 1999

TOTAL TIME 995.95 smo TACH. 1709.3

I CERTIFY THAT THIS Propeller
 HAS BEEN INSPECTED IN ACCORDANCE WITH

A Propeller INSPECTION AND WAS
 DETERMINED TO BE IN AIRWORTHY CONDITION

ANTHONY D. CASEY

A&P 251967817 IA

[Signature]

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
MAR 18 1999	H.N 1709.3	Reinstall prop to #2 (Right) position on Piper Aztec N159B serial number 27-7754047. INSTALLATION PERFORMED INW Piper Service Manual part no. 753 S44. GREASED and SERVICED prop.	
		ANTHONY D. CASEY A&P 251967817 <i>Anthony D. Casey</i>	CITY OF SPARTANBURG SPARTANBURG DOWNTOWN AIRPORT 500 AMMONS ROAD SPARTANBURG, SC 29306 (864) 574-8560
DATE MAR 18 1999	TOTAL TIME <u>975.95</u> TACH. <u>1709.3</u>		
I CERTIFY THAT THIS <u>Propeller</u> HAS BEEN INSPECTED IN ACCORDANCE WITH			
A <u>Visual</u>		INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION	
ANTHONY D. CASEY		A&P 251967817 IA	
		<i>Anthony D. Casey</i>	

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
03/16/04	2244.7	Removed Prop from right engine of N159B. Prop goes to feather on engine shutdown.	Anthony D. CASOY AEP 25596781710 <i>[Signature]</i>
3/19/04		Desludged propeller m/w HC-E24R-2RB5 s/n BP8278, C/W SB 148A H & H PROPELLER SERVICE, INC. 3439 SOUTH AVIATION DRIVE BURLINGTON MUNICIPAL AIRPORT, BURLINGTON, N. C. 27215 FAA REPAIR STATION PS4R451M 1-800-334-6437	<i>[Signature]</i>

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
MAR 22 2004		HM 2242.7 REINSTALLED Propeller Held propeller Avionics D CM7 A41251967817 IA.	<i>[Signature]</i>
DATE <u>DEC 05 2004</u>			
TOTAL TIME <u>1331.8</u>		TACH. <u>2265.2</u>	
I CERTIFY THAT THIS <u>Propeller</u>			
HAS BEEN INSPECTED IN ACCORDANCE WITH			
A <u>Annual</u> INSPECTION AND WAS			
DETERMINED TO BE IN AIRWORTHY CONDITION			
SIGNATURE <u>[Signature]</u>			
CERTIFICATION NO. <u>A-P-237482541 IA</u>			

