

 TELEDYNE CONTINENTAL



Gold Medallion Aircraft Engine

REBUILT ENGINE LOG

N4382A

AIRCRAFT N NUMBER

JD-550-B

ENGINE MODEL NUMBER

549216-R

ENGINE SERIAL NUMBER

Gold Medallion® Warranty protection

All Teledyne Continental Motors engines delivered as original equipment after January 1, 1980 are protected by TCM's exclusive Gold Medallion Warranty. This new warranty provides extended protection to the TBO of your engine. See your TCM distributor for all the facts or write direct to Teledyne Continental Motors for a free brochure.

Service Information

Service Bulletins and Technical Publications are available on a direct mail basis from the factory. Orders must be prepaid. Send for order form or call (205) 438-3411, publications department, for information.


 **TELEDYNE CONTINENTAL MOTORS**
Aircraft Products Division

P. O. Box 90 • Mobile, Alabama 36601

This engine model T0550B4F, Serial No. 249216-R
was rebuilt on 6/21/89 by Teledyne Continental Motors in
accordance with approved design data and the applicable requirements
of Part 21 of the Federal Aviation Regulations. The approved design data
for this engine incorporates all changes required by applicable Air-
worthiness Directives and Teledyne Continental Motors Service
Bulletins.

TELEDYNE CONTINENTAL MOTORS

Walter Roque

 TELEDYNE CONTINENTAL MOTORS
Aircraft Products Division

ENGINE DESCRIPTION

TYPE TCM MODEL T0-550-B SERIAL NO. 249216-R

RATED H.P. _____ MAXIMUM H.P. _____

RATED R.P.M. _____ MAXIMUM R.P.M. _____ OIL PRESSURE _____

BORE _____ STROKE _____ DISPLACEMENT _____ CU. IN. _____

COMPRESSION RATIO _____ GEAR RATIO _____

PROPELLER _____ HUB DESIGN _____ HUB SERIAL NO. _____

BLADE DESIGN _____ BLADE SERIAL NO. _____ BLADE SERIAL NO. _____

MAXIMUM HUB H.P. _____ MAXIMUM BLADE H.P. _____

PITCH _____ DIAMETER _____ LENGTH _____

OWNERS NAME DAVID J. Friis

ADDRESS 11100 Snowline Dr. CITY ANCHORAGE STATE AK 99516

ENGINE LOG

DATE	R.P.M.		TIME ON GROUND			TIME IN AIR			TOTAL TIME		REPAIRS - ADJUSTMENTS	SIGNATURE	LICENSE NUMBER
	Ground	Air	Hrs.	Min.	Total	Hrs.	Min.	Total	Hrs.	Min.			
	THIS AIRCRAFT AIRCRAFT ENGINE PROPELLER AN APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE.												
	REPAIRMENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER ORDER NO. <u>8411</u> DATE <u>10/4/89</u>												
	SIGNED <u>R. J. Wall</u> <u>ACI</u> FOR												
	(SIGNATURE OF AUTHORIZED REPRESENTATIVE)												
	BUD'S AIRCRAFT <u>CJ4R104M</u>												
	CERTIFICATE NO.												
	(ADDRESS)												
	BUD'S AIRCRAFT 8211 Resurrection Bl. Anchorage, Alaska 99504												
			BUD'S AIRCRAFT C.R.S. 501-33 A/F-1-3 ANCHORAGE, ALASKA 99509										
			CHANGED OIL 11 qt MOBIL ONE CHANGED OIL FILTER CH48109										
	BROUGHT FORWARD												
	TOTALS												

ENGINE LOG

DATE	R.P.M.		TIME ON GROUND			TIME IN AIR			TOTAL TIME		REPAIRS - ADJUSTMENTS	SIGNATURE	LICENSE NUMBER
	Ground	Air	Hrs.	Min.	Total	Hrs.	Min.	Total	Hrs.	Min.			
4/18/91	TASK 3060		24	15		24	15		24	15	Completed: oil & filter changed. (customer oil)		
	COMP ENG #1		24	15		24	15		24	15			
BROUGHT FORWARD													
TOTALS													

DATE
4/18/91
PILOT
5060

CERTIFY THAT THIS ENGINE
HAS BEEN INSPECTED IN
ACCORDANCE WITH 100 HRS
AND WAS DETERMINED TO
BE IN AN AIRWORTHY
CONDITION. D. GLUECK ASP #141796304

