

 TELEDYNE CONTINENTAL



# Gold Medallion Aircraft Engine

# REBUILT ENGINE LOG

N4382A

AIRCRAFT N NUMBER

JD-550-B

ENGINE MODEL NUMBER

549216-R

ENGINE SERIAL NUMBER

## Gold Medallion® Warranty protection

All Teledyne Continental Motors engines delivered as original equipment after January 1, 1980 are protected by TCM's exclusive Gold Medallion Warranty. This new warranty provides extended protection to the TBO of your engine. See your TCM distributor for all the facts or write direct to Teledyne Continental Motors for a free brochure.

## Service Information

Service Bulletins and Technical Publications are available on a direct mail basis from the factory. Orders must be prepaid. Send for order form or call (205) 438-3411, publications department, for information.


 **TELEDYNE CONTINENTAL MOTORS**  
Aircraft Products Division

P. O. Box 90 • Mobile, Alabama 36601

This engine model T0550B4F, Serial No. 249216-R  
was rebuilt on 6/21/89 by Teledyne Continental Motors in  
accordance with approved design data and the applicable requirements  
of Part 21 of the Federal Aviation Regulations. The approved design data  
for this engine incorporates all changes required by applicable Air-  
worthiness Directives and Teledyne Continental Motors Service  
Bulletins.

TELEDYNE CONTINENTAL MOTORS

*Walter Roque*

 TELEDYNE CONTINENTAL MOTORS  
Aircraft Products Division

## ENGINE DESCRIPTION

TYPE TCM MODEL T0-550-B SERIAL NO. 249216-R

RATED H.P. \_\_\_\_\_ MAXIMUM H.P. \_\_\_\_\_

RATED R.P.M. \_\_\_\_\_ MAXIMUM R.P.M. \_\_\_\_\_ OIL PRESSURE \_\_\_\_\_

BORE \_\_\_\_\_ STROKE \_\_\_\_\_ DISPLACEMENT \_\_\_\_\_ CU. IN. \_\_\_\_\_

COMPRESSION RATIO \_\_\_\_\_ GEAR RATIO \_\_\_\_\_

---

PROPELLER \_\_\_\_\_ HUB DESIGN \_\_\_\_\_ HUB SERIAL NO. \_\_\_\_\_

BLADE DESIGN \_\_\_\_\_ BLADE SERIAL NO. \_\_\_\_\_ BLADE SERIAL NO. \_\_\_\_\_

MAXIMUM HUB H.P. \_\_\_\_\_ MAXIMUM BLADE H.P. \_\_\_\_\_

PITCH \_\_\_\_\_ DIAMETER \_\_\_\_\_ LENGTH \_\_\_\_\_

---

OWNERS NAME DAVID J. Friis

ADDRESS 11100 Snowline Dr. CITY ANCHORAGE STATE AK 99516



## ENGINE LOG

DATE	R.P.M.		TIME ON GROUND			TIME IN AIR			TOTAL TIME		REPAIRS - ADJUSTMENTS	SIGNATURE	LICENSE NUMBER
	Ground	Air	Hrs.	Min.	Total	Hrs.	Min.	Total	Hrs.	Min.			
	THIS AIRCRAFT AIRCRAFT ENGINE PROPELLER AN APPLIANCE IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE.												
	REPAIRMENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER ORDER NO. <u>8411</u> DATE <u>10/4/89</u>												
	SIGNED <u>R. J. Wall</u> <u>ACI</u> FOR												
	(SIGNATURE OF AUTHORIZED REPRESENTATIVE)												
	BUD'S AIRCRAFT <u>CJ4R104M</u>												
	CERTIFICATE NO.												
	(ADDRESS)												
	BUD'S AIRCRAFT 8211 Resurrection Bl. Anchorage, Alaska 99504												
			<u>Ins. O/W 100 Hours/Annual</u> <u>TT. AT 3834.99</u> <u>TT. Engine 31.46 SMOH</u> <u>TT. Prop 78.80 SOH</u> <u>Tach time 2003.32</u> <u>A/D's thru serial 89-19</u> BUD'S AIRCRAFT C.R.S. 501-33 A/F-1-3 ANCHORAGE, ALASKA 99509  <u>CHANGED OIL 11 qt MOBIL ONE</u> <u>CHANGED OIL FILTER CH48109</u>										
BROUGHT FORWARD													
TOTALS													



