


ENGINE LOG



PIPER AIRCRAFT CORPORATION

ENGINE LOG

PIPER AIRCRAFT CORPORATION

General Offices at
Lock Haven, Pennsylvania
U. S. A.

Part No. 230 716

OWNER

NAME	ADDRESS	Installed in Aircraft No.	Date
1		N56353	
2			
3			
4			
5			
6			

If this book is found, please return it to the owner.

NOTICE

Making false entries in this book is a violation of government regulations and is punishable by civil penalty.

ENGINE LOG

Date	Engine Time		Recorder Reading	Maintenance
	This Date	Since Major		
10-31-73	Brought Forward →		53 Hours.	
	Completed 50 Hour Inspection as per Piper Suggested 50 Hour Inspection Sheet. Changed oil #50 Phillip N/O.			
			ER Good	
			MIDWEST PIPER SALES, INC.	
			Certified Repair Station #3137	
			"Your Piper Dealer"	
			Wichita, Kansas	
Total To Carry Forward				

and Remarks

Signature

Certificate No.

DATE MAY 28 1974 BAKER'S FLYING SERVICE

Has performed the following service

Oil change Replace oil filter

Checked & cleaned oil screen

Run aircraft & checked for leaks

Time required 154

Cal G. Keam

ATP 2013465

7 QTS Sheol SOWT
OF 11A QILTER.

ENGINE LOG

Date	Engine Time		Recorder Reading	Maintenance
	This Date	Since Major		
7-13-74	Brought Forward →		181 Hours	
	Checked Engine Compression Replaced Ignition wires #4 cyl. R. Mag. Installed Intake Rotating Valve Kit # LW 13677 + New Rings # 14 #2 cyl's no oil or Filter change.			
	"I certify that this engine has been in- spected in accordance with a 100-hour inspection and was determined to be in airworthy condition."			
	Signed <u>E. R. Good</u> for			
	MIDWEST PIPER INC. Certified Repair Station #3137 "Your Piper Dealer" Wichita, Kansas			
Total To Carry Forward				

