



***AERO PROPELLER
and Accessories, Inc.***

PROPELLER LOGBOOK

(303) 469-1749 USA: 1-800-525-8756 CO: 1-800-367-5434
3400 Industrial Lane, Unit 8, Broomfield, CO 80020

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
NOTE: Enter Compliance With All Applicable				

REPAIR STATION #S60-110

WORK ORDER #8920
 JULY 26, 1990
 A.D. COMPLIANCE ONLY, PERFORMED IN ACCORDANCE WITH..
 S.M.: 113B, 133B.
 S.L.: N/A
 S.B.: 159A
 S.I.: N/A
 S.A.: N/A
 A.D.: 77-12-06 EXCEPT TACH SECTION, 90-02-23
 RECOMMENDED TBO: 5 yrs/2000 hrs.
 S/N: CH22372 BLADE S/N: 1) D84589 2) D84491
Robert Kessinger
 PR522119738 AERO PROPELLER & ACCESSORIES, INC.

806-328-5347

TO m
PROP

TOTAL TIME 134.19

DESCRIPTION OF WORK ACCOMPLISHED

Make HARTZELL PROPELLER Model HC-C2YK-1BF/F7666A-2

S/N CH22372 Blades 1. D84589 2. D84491 3. _____ 4. _____

Overhauled _____ Blade Replacement _____ Blade Repair _____ Reseal _____

Repitch _____ Other A.D. COMP Service Manual 113B, 133B

Service Letters N/A

Service Bulletins 159A

Service Instructions N/A

Through AD77-12-06 except tach sec. 90-2-23 Boot P/N N/A

Remarks A.D. COMPLIANCE ONLY, PERFORMED IN ACCORDANCE WITH 113b, 133B.

Pitch Settings: Low 14.0 High 29.5 Reverse _____

Feather - Latch -

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
4/10/2013	1340.19		Eddy Current inspected hubs S/W	CH22372E in
			accordance with AD 2009-22-03 and SB 61-269 Rev 6. No defects noted.	
			next inspection due in 100 hrs. Porterfield Propellers FAACRS#ZNR670K	
			Jim Porterfield	
Aug 6-2013	1340.19		Dressed & ground prop. A/B Prop for AD note above	
			Carter/each in AP 10779283	
NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12				

DATE: 01-15-2015

N: N 56353

TACH: 1354.64

PROP: Hartzell HC-C2YK-1BF

S/N: CH22372E

TSPOH: 243.64


Y

Complete Annual inspection. Inspect blades, hub, spinner and bulkheads. Propeller removed for crankshaft seal replacement, and reinstalled with new seal. ECI inspection due @ 1440.19

ins
tion
ers

I certify that this **PROPELLER** has been inspected in accordance with an **ANNUAL** inspection and was determined to be in an Airworthy Condition.

Larry Hallock
IA 2239535



Professional Aircraft Services

4824 Earhart Rd, Loveland, CO 80538
970-679-4633

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12