ENGINE LOG A4527W

SSP-1872-1


652 Oliver Street Williamsport, PA 17701 U.S.A. 570/323-6181

IN SERVICE DATE 062407 ENG.

DETACH AND RETAIN THIS PORTION FOR YOUR RECORD

652 Oliver Street Williamsport, PA 17701 U.S.A. 570/323-6181

ENGINE LOG AND MAINTENANCE RECORD



TLRED-489 (Rev. 10-96)

652 Oliver Street Williamsport, PA 17701 U.S.A.

This engine has been overhauled/rebuilt in accordance with the applicable Textron Lycoming manuals. All applicable Federal Aviation Administration Airworthiness Directives and Textron Lycoming Service Bulletins have been complied with. All parts have been inspected and have been determined airworthy to return to service. All accessories as part of the type certificate are either new or newly overhauled. Refer to enclosed Form ET001 for applicable accessory part numbers and serial numbers.

Engine Model:

Serial #:

Total Time:

Work Order #:

Date Completed:

O-320-D3G

RL-12003-39A

0.0

GJ159903

5/3/01

Authorized Signature

Textron Lycoming 652 Oliver Street

Williamsport, PA 17701 Repair Station: EJ1R115K

_					
9	0	2	N	0.	
J				v.	

E.M.C. AVIATION SERVICES

351 AIRPORT ROAD NOVATO, CA. 94945 (415) 892-9234 fax (415) 892-7544

"N" N9527W DATE: 06/24/2001 MAKE/M: LYC. O-320-D3G SERIAL: RL-12003-36A

TACH: 4102.6 **TOTAL**: 0.0

THE FOLLOWING WORK PERFORMED:

INSTALLED FACTORY REMAN LYCOMING ENGINE MODEL O-320-D3G S/N RL-12003-36A IN ACCORDANCE WITH STC # SA413CH. SEE 337 FORM FILED. INSTALLED ENGINE USING NEW LORD MOUNTS, OIL COOLER, AND RUBBER HOSE KIT. ORIGINAL PROPELLER, ALTERNATOR, AND PRIMER SYSTEM WERE INSTALLED. SERVICED ENGINE WITH 8 QUARTS AEROSHELL 100 MINERAL OIL. GROUND RUN GOOD, NO LEAKS NOTED.

Signiture Signiture

Certificate # 572578187 A&P

Page Total	All Repair Data Must Bear the Endorsement of
Brought Forward	Certificated Mechanic, and his Rating and
Total to Date	Certificate Number MUST be Shown.

ENGINE LOG Serial No. License Number E.M.C. AVIATION SERVICES 351 AIRPORT ROAD NOVATO, CA. 94945 (415) 892-9234 fax (415) 892-7544 "N" N9527W DATE: 09/07/2001 MAKE/M: LYC. O-320-D3G SERIAL: RL-12003-36A 39 A TACH: 4128.4 TOTAL: 25.8 THE FOLLOWING WORK PERFORMED: CHANGED OIL AND FILTER. SERVICED ENGINE WITH 8 QUARTS AEROSHELL 100 MINERAL OIL. REPLACED ALCORE EGT PROBE. GROUND RUN GOOD, NO LEAKS NOTED. Certificate # 572578187 A&P Signiture All Repair Data Must Bear the Endorsement of a Page Total Certificated Mechanic, and his Rating and **Brought Forward** Certificate Number MUST be Shown. **Total to Date**

Time REPAIRS - ADJUSTMENTS - SERV	VICE - REMARKS Signature Licen
Hrs Min	
18,4 HOS + NOS INSTRUCTOS	ATTHE INSTRUMENT FOR LEASE MAIN BUT AN HOSES, LINES, & MARRIMAN THUS BUT LEASE CHEEKS & CHEMINA FOR THIS BUT WE HAS BEEN INSPECTED TO THIS BUT OF PUTTED AND IS DEFORMENT CHANGE INSPECTOR BOULDANDS LINES BOOKESEES
Page Total Brought Forward	All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.
Bro	

-	, http://www.	ENGIN	E LOG Se	rial No	License
	ime REP	PAIRS - ADJUSTMENTS - SERV	ICE - REMARKS	Signature	Numbe
DATE: 11/4/03 ENGINE S/N L-	12003-39A 100 HR	REG#:9527W TSO 133.5 WO#: 2912	ENG. TYPE: 0-320-D3G TACH: 4236.1 ENGINE TOTAL TIME: 13	3.5	
			NGED THE OIL AND FILTER, SERVICED AMINATES OK. THE SPARK PLUGS WEI ION AIR FILTER ELEMENT. REPLACED		
aler i i		11 VV -1 10 D			

Total to Date

Certificate Number MUST be Shown.



Changed oil and filter. Checked for defects and metal. None found.

Removed, cleaned, gapped, tested, inspected and installed sparkplugs w/new gaskets. Performed compression check: All 78/80.

Ran up engine and ops checked, All checks ok.

Cleaned engine and engine compartment.

The components identified above were repaired and inspected IAW Federal Aviation Regulations and were found to be in an airworthy condition for return to service.

Signed: Dated: 4/1/05 N#: 9527W Lisa Tyler IA623048610

Tach: __4265.9___TTSN:__4265.9__TSMOH: _163.3__ For more info see__w/o #_2380_ 145 John Glenn Drive, Concord, CA. 94520 T: (925) 676-2100 F: (925) 676-5580



145 JOHN GLENN DRIVE CONCORD, CA. 94520

T: (925) 676-2100 F: (925) 676-5580

I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED IAW. ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.

TIS: 4	ISA TYL	ER, IA62301 TSMOH:_	6610		1-1-05 15274
Must Bear the Endorsement of hanic, and his Rating and er MUST be Shown.				Signature	Serial No.
0			111	Licens	

Date		SkyView Aviation	SkyView Aviation, LLC 21901 Skywest Drive Hayward, CA 94541 (510)785-7666	ure	License Number
	Hrs	N Number: N9527W Tach: 4345.27 SM	10H:242.6		
_		Eng. TT: 242.6			
		Complied with 100Hrs inspection in accordance wit and FAR 43 appendix D. Changed oil and filter. Inst Aeroshell 100w50 and oil filter CH48110-1. Inspecte contamination, none found. Checked timing, cleaner spark plugs. Compression: 1) 75/80, 2) 74/80, 3) 74/carburator heat shroud. For AD information see ad literation washed down and test run, no leaks were found to be airworthy.	alled eight (8) quarts of d old oil filter for d, gapped and tested all (80, 4) 74/80. Patched st dated 03/09/2006.		
		cichard Ortenheim A&P 2517877		nent of a	

ENGINE LOG Serial No. Time Date License Number **REPAIRS - ADJUSTMENTS - SERVICE - REMARKS** Signature Hrs Min ENGINE MODEL: AIR WEST Air West Aircraft Engines DATE: 7/17/2006 ENGINE S/N: AIRCRAFT ENGINES REG. NO: 9527W A/C TSN: Repair Station No. TV3R881L WORK ORDER: 13168 670 Airport Blvd. ENG TT TACH: 4353.4 San Carlos, CA 94070 Phone: (650) 593-8403 **Engine Entries** Cleaned #2 and #4 primer nozzles. Cleaned, gaped, tested and reinstalled all spark plugs. Checked mag timing. Installed "P" leads in correct position. Engine start and ground checked good... The component(s) and/or discrepancy (ies) identified on this work order, to the above mentioned aircraft were repaired and inspected in accordance with current Federal Air Regulations and were found air typic thy for return to service. DATE: 7/17/2006 SIGNED: Work Order: 13168 Abdi Anvari Printed by EBis 3 (datcomedia.com) Certified Repair Station No. TV3R881L Page Total All Repair Data Must Bear the Endorsement of a **Brought Forward** Certificated Mechanic, and his Rating and Certificate Number MUST be Shown. Total to Date

		SkyView Aviation 21901 Skywest Drive		
	Ti	(511)1/85-/000	— е	License
Date	Hrs	N Number: N9527W Tach: 4386.04 SMOH: 283.37 Eng. TT: 283.37 Complied with 100Hr inspection in accordance with Piper Service Manual and FAR 43 appendix D. Changed oil and filter. Installed eight (8) quarts Aeroshell 100w50 and oil filter CH48110-1. Inspected old oil filter for contamination, none found. Checked timing, cleaned, gapped and teste spark plugs. Compression: 1) 78/80, 2) 72/80, 3) 74/80, 4) 72/80. AD2007-04-19R1 Cylinder seperation N/A by Date For further AD information see ad list dated 04/01/2006. Engine washed down and test no leaks were found. Engine determined to be airworthy. Richard Ortenheim A&P 2517877	run,	Number
		Date: 06/26/2007 X Certificate Number MUST be Sh		of a

SkyView Aviation, LLC

Total State of the last		ENGINE LOG S	erial No.	
Date	Time Hrs Min	REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
3 May Ut Che Rotated	a 10		leaned gaped	+
file Mag	Adde	AD's 06-12-07 N/A 07-04-19 N/A	07-04-19 R1	w/A
AD- F	15-26- ine R	eplacement Due June 2009. Chamed 20 Leats Notel - Tartalled Overhanded	fuel Screen	ump.
RSE NE	5 ROB	4N. WO# 132530 - I certify this Engal	her time Be	reperto
		Page Total Brought Forward Total to Date ADP Soll & FOR TOTAL All Repair Data Must Bear Certificated Mechanic, and Certificate Number MUST	d his Rating and	

Aviation Specialties ial No. 301 County Airport Rd Hangar A-4 Vacaville Ca 95688 License N#: 9527W Engine Lycoming 0-320 Work Order: 1099 Time Signature Engine S#: RL-12003-39A Number TSN 322 Tach/Date: 8-1-09 4424.6 Date Min Hrs Engine: The engine identified above was repaired and inspected in accordance with current maintenance rules under the FARs and is approved for return to service with respect to the work performed below. 100 hr inspection and service per Cessna MM checklist. Serviced spark plugs and performed compression test as follows: #1 78, #2 76, #3 75, #4 75. Installed plugs with new M-674 gaskets. Drained oil and inspected filter. Replenished sump with 8 Qts Aeroshell W100. Installed new CH48110 filter. Replaced oil cooler lines with Type D hoses Per AD 95-26-13 due 5424 or 4-2017 Washed down engine I Certify that this engine has been inspected in accordance with a 100 hr inspection and was found to be in airworthy condition. Brooks R. Mayes AP 569453224 he Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown. **Brought Forward** Total to Date

Serial No.

Date

Time Hrs Min

REPAIRS - ADJUSTMENTS - SERVICE - REMARKS

Signature

License Number



SUBURBAN AIR

20511 Skywest Drive Hayward, California 94541 (510) 780-0428 ENGINE ENTRY

JOB: 1776 AIRCRAFT: N9527W TACH: 4458.9 TSOH: N/A TTE: 356.3

MODEL: Lycoming O-320-D3G S/N: RL-12003-39A

DATE: 3/1/2011

Compression results: #1-78/80, #2-76/80, #3-76/80, #4-76/80. Drained oil. Removed and replaced oil filter with new (P/N: AA48110-2). Examined old oil filter element and suction screen, no defects noted. Serviced engine with 8 quarts Aeroshell W80 Plus oil. Cleaned, gapped and tested spark plugs. Rotated and re-installed spark plugs using new gaskets (P/N: M-674). Verified AD's current through AD 2009-26-12. AD 98-02-08 "crankshaft failure" due 5/3/2011. All work completed in accordance with the Piper PA-28 and Lycoming Service Manuals. -END

I certify that this engine has been inspected in accordance with FAR 43 Appendix D (Annual Inspection) and has been determined to be in an unairworthy condition. A list of discrepancies dated 3/1/2011 has been provided for the aircraft owner and operator.

Brandon Thompson A&P / IA 3212565

1/4

ENGINE LOG 98-02-02 4458.

Serial No.

Date	Tit	me	REPAIRS - ADJUSTMENTS	- SERVICE - REMARKS	Signature	License Number
MY			CHECKLIST - All I	OF THIS ENG-PERPARTY		PP.D -
POIL	SE DM	EVX ON	B-FMOUNT/SYST.C MYDIFF. LIST AN CYLS MITS=INSTALLED	Date TULY OF, ZOIL	TACH 4	458 -
NEW NEW C/W AZ		7-02 FT	NATOR BELT OB INSPOF ZORE-NO PITING	I certify that this aircraft engine required 91-407(d), IAW Part 43 inspection and has been found a TTAF: 4458	for annual /100 irworthy.	ted as
SHA	33	6 H	Page Total Brought Forward Total to Date	A/PIA 1426586 Start SCOL	MICK.	

	ENGI			NE LOG Serial No.		
Date	Ti	me	REPAIRS - ADJUSTMENTS - SERVICE - F	Signature	License Number	
Date	Hrs	Min	100	TIME LIMIT HAS BEEN	- Tilber	
	100		11/64 110		-	
		TV	0 ST DEN IR AIF 1428566			
-Helle	4	XX	CENTER OF A	have ingreation elle	1/ 211	
06/00/15	1456	5.9	presoned a prepure		3612	
1			for lerrying to main	larrane facilty. Mulsim DI	avidyon 1	
1.1-			increated enine no	annual inspection		
1,15/15			1115/1001	8/20 7 75/80		
			chell (37, compassion			
7 4 1			3/72/30 4 73/80 , Die	ined oil and		
			1 /1 1 Cilling Carrier	ed with 895		
	-	-	replaced film, service	Last Cobrholis		
			of 100w, cleaned and	1 helle cealweel-Z		
			lound por find orach	d sort in		
		- /	Page Total	All Repair Data Must Bear the Endorsement	t of a	
			Brought Forward	Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.		
	-	-	Total to Date	Certificate Number Moot be shown		

ENGINE LOG Serial No. License Time Signature Number **REPAIRS - ADJUSTMENTS - SERVICE - REMARKS** Date Min checkel Inspection labor Gardyar dirworthy condition Approval for Return to Service I certify that the aircraft or component identified above has been repaired and / or inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service with respect to the work performed. Pertinent details of the repair are on file at this agency under the above Work Order No. ndorsement of a lating and M. Gavrilyuk for CRS# PCPR439B Date lown.

Date	Ti	me	REPAIRS - ADJUSTMENTS - SERVICE - REMARKS		Signature	License Number		
riis Willi								
3/19/0			Complied with 100hrs	inspection IAW				
11			order service monul	and FAR43				
			appendix D. change	1				
			Serviced with 1000					
			448110-1, cleaned a		S.			
			ompressions # 18/80 #2	701/20 #3 /7/80 #9.	19/90			
10.10				ee ontrave los.	1/Rosest	2110		
			leplaced nose time - si	ev j	3635			
			Fach 4575.73 hol	bs 134.0 °	/			
			Page Total	All Repair Data Must Bear	the Endorsement of a			
			Brought Forward	Certificated Mechanic, and Certificate Number MUST to	his Rating and			
			Total to Date	Certificate Number Wost	o onown.			

Date	Time Hrs Min	REPAIRS - ADJUSTMENTS - SERVICE - REM	ARKS	Signature	License Number
Tel dina		Tach 4675.58 Comple	I will coon	repeating	
18/04/11		check ligh per lycomy	MM and FI	12 43	
1		appendix D. changed	oil and filt	- 6gh.	
-		PHUS110-1 cleens and	Jest speed	olis.	1000
-		Congassion #1,72 #2	75 #3, 77	#478/80	
-+		, ,	ren Good.		3, 400
-			Mehsan	Correlich	
-+			A4P 31	3550	
				com	
Tile		BLED LECT BRANC 18	E khoile At	1594791	
1/2/13			All Repair Data Must Bear		77
			Certificated Mechanic, and Certificate Number MUST		

Date	Ti	ne	AD INCOMENTS CERVICE	DEMARKS	Signature	Lie
Date	Hrs	Min	REPAIRS - ADJUSTMENTS - SERVICE -			License Number
11/19/15	47	4912	CHANGER OIL & BILTER. 70	OTS PHILLIPS XC20	50w	-
1-11-		1119	CHAMPION OIL FICTOR EN	48118-1, OIL SUET	1200 TEV	
			CUT OPEN & INSTECTAD.	BOTH CLEAN, GNO	INBRUN-	
				= solveits 17		
			BOOK BUILDING BUILDING		1776	
1-11.1	422	500	THEHTIME. COMPLIED	world lander 11	CP 11550	
10/10	177	100	MM & CAR 43 APPENDE	ONTH TOOKE PA	200	COMIN
		9	am ferr 42 Kryens	VIX LI. SPARK FEE	CO CLERNDE	DITE
	1					
1		1	MAG. TIMING CHECKED,	ALL AD'S COMPLIE	D WITH EN	61215
/		,	NIRWORTHY. K.E.	Ledwith 694	1594791	
			Page Total	All Repair Data Must Bear t	he Endorsement of a	
			Brought Forward	Certificated Mechanic, and	his Rating and	
			Total to Date	Certificate Number MUST b	e Shown.	

		me	REPAIRS - ADJUSTMENTS - SERVICE - R		Signature	License Number
Date	Hrs	28	TACK TIME REPLACED A	ACT. WITH USED		
01/09/10	100	1	AIR MORTHY ALT. ENG. MO	DUTING BEACKED		
		/	FALT. ADSUSTMENT ARM	REPURCED, 101,		
	1		JOWER TO COL BREAKE RE	SPAIRED FROM THU	ED.	
	1		CHANGET OIL FEILTER. 6	ats PHILLIPS XC	-20-50W.	
-			CHARPION OIL FILTER CH			
			SURTION SCREEN CLEAR GULTER GUT OPEN FPL			
7			ENG. RUN. NO LEAKS.	KI Ledwill	A9P159	4791
4			Page Total Brought Forward	All Repair Data Must Bear Certificated Mechanic, and	the Endorsement of a his Rating and	
	-		Total to Date	Certificate Number MUST	be Shown.	

1016 Date	Ti	me	REPAIRS - ADJUSTMENTS - SERVICE - REMARKS		Signature	License Number
-	Hrs	Min	REPAIRS - ADJUSTMENTS - SERVICE		0	- Siliber
1/21	48	16,7	BENDLY STAKTER REP	MIRED TO AIRWORTH		
		/	- I WENT TO BE	RUSHENARTH		
	/		PAR MIX BRILL	CHEFTHOED, NOTCH	77.42	
			DENIGOS TO ANCALORI	A STATE OF THE STA		-
			ROTOR & STATEL REPLI	ACERS AIR CREET		
			1 00 TO 6/16/	T STATES I		
			2	7 6 LEWENTY		-
				A\$\$ 1894791		-
				Color Maria Walant		-
			Page Total	All Repair Data Must Bear Certificated Mechanic, and	his Kating and	
			Brought Forward	Certificated Mechanic, and	be Shown.	
			Total to Date			

Section 1		-210	INE LOG	LOG Serial No.		
	144.			Signature	License Number	
STATE OF THE PARTY	Time	REPAIRS - ADJUSTMENTS -	SERVICE - REMARKS			
Date 2/6	Hrs Min			DIFER SERVICE MAI	doncit	
118	4871.41	COMPLIED WITH	100 NE. INST. IN	E. FILTER CUT OPER	A FOUND	
	/	BRY3 PARTD. CA	VANGET TITLE	CATHERT CICTE	P. NEW	
	X	NO DEFOSITS. 60	TSTATECHSKER	ANTERIUS CLE	ANED GAR	
	/	TEMPEST SPARK	# 1 1 1 37/0	# 76/80 #4 74/	DO, MAG	
		THING CHECKED	12, 1/80 01/10	VIED WITH ENGH	E 15 AIRU	
/			16	16.		
	100111	REPLACED DRAIN	1 1 H (all) (al	THE MEET AIRWE	SETHY	
105 4	4844.16	REPLACED DRAIN	VIVE PERU	INC TICKE WITH	EUPPEST	
		TUBE. REPLACED	LOWER STARKE TO	1007 11:05 PP	DIOCETT	
1		UREMHOE, INSPECT	TROO WILERIEN TEN	1010 1000,101		
-		Page Total	All Repair Data N	Must Bear the Endorsement of a	a (20101.)	
T	100	Brought Forward	Certificated Meci	er MUST be Shown.		
1		Total to Date				

160		ENGINE LOG	rial No.	
20 P	Time Hrs Min	REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
03/05	489416	FOUR BHILDST GASKOTS: ENGLING WASK	\$ (MOROCE CE)	CHECKED
The state of the s		LAR LEAVE PRETIDENTED TO FIT SIAI	E hed will	2
		16;	FP159474	31
	# # S	coident/incident at Lincoln, CA on 4/4/16 endering it beyond economical repair per insurance policy provisions. for further information refer to claim file #: HIG\$4874/1 ligned by: Date: 9/20/16 id Republic Aerospace, Inc.		
=		Brought Forward Total to Date All Repair Data Must Bear Certificated Mechanic, and Certificate Number MUST	nis nating and	

Date	Time Hrs Min	REPAIRS - ADJUSTMENTS - SERVICE - REMA	RKS	Signature	License Number
-	the	4 9195.5 Smo4 855.0	INSTALLED >	HIS ENGIN	
6-17-17		ON PA-28-161 8/016 BO	TH MAGS HU	20 500 Ins	Trettam
		BY AIRCRUPET MAGNETO S,	ERVICE NEW	mAL LINA	NECC
		OVERHAULIED FUILL PUMP	CLEAN & GA	AP SPARK	Pluce
		OIL & FILTER CHANGE ADDE	0 7 0+5 15	50 AN NU	10 10
		CRANKSHAFT GEAR METAINI	WE BOLT C/	W BY NEP	VACINE
		CRANK GRAN BOLT & INS	Prect 102 F	+1130 Ans	BRE
_		CURTENT. PERFORMED NUN	UP & LEAK	C4 APBRO	VEP ROR
-		RETURN TO SÉRVICE. 1	VEXT PAGE		
-					
-		Page Total All	Repair Data Must Bear	he Endorsement of a	
7		Brought Forward Ce	rtificated Mechanic, and rtificate Number MUST b	his Rating and	

The last of	T	me			Ciana	
Date	Hrs	Min	REPAIRS - ADJUSTMENTS - SERVICE -		Signature	License
-17-17			I CERTIFY THIS TENGIN AN ANNUAL INSPECT	E WAS INSPI	CTED IN	
			AN ANNUAL INSPEC	TION AND FOU	WP AIRS	made 1
			Scott Olson	AP 258 3577 I	2	TOTAL Y
1 4	1.1					
	7- 1					
	3		The state of the s			
		-				
			The state of the s		Charle in	
	1.4		Page Total	All Repair Data Must Bear	the Endorsement of a	
			Brought Forward	Certificated Mechanic, and Certificate Number MUST I	his Rating and	
			Total to Date	Certificate Number MUST	be Shown.	