

LH



# ***TIFFIN AIRE INC.***

**3861 Co. Rd. 140  
Findlay, Ohio 45840  
1-800-553-7767  
Fax 419-299-3244**

**Propeller Log Book**

LH

Stack /

Owner Name \_\_\_\_\_

Address \_\_\_\_\_

Propeller Make Hartzell \_\_\_\_\_

Propeller Model HC-82YR-2RBSF \_\_\_\_\_

Blade Model F8465B-7R \_\_\_\_\_

Hub Serial No. BP2506 \_\_\_\_\_

Blade Serial No. 1 H97432 \_\_\_\_\_

2 H97434 \_\_\_\_\_

3 - \_\_\_\_\_

4 - \_\_\_\_\_

PITCH RANGE

High 20.7° \_\_\_\_\_ Low 14.5° \_\_\_\_\_

Feather 80.2° \_\_\_\_\_ Reverse - \_\_\_\_\_

Maximum Hours or Service Life between overhaul required by Mfg. 2000 Hrs. or 5 \_\_\_\_\_

years interval between overhauls. \_\_\_\_\_



Blade #1\_E84658-7  
Blade #2\_E84658-7  
Blade #3  
Blade #4

Overhaul  
Compl. Numbers  
Compl. #  
Compl. #

# ANCE & SERVICE HISTORY

Signatures  
and Station  
Numbers

06/10/97

Propeller Total Time UNKNOWN

Propeller/Hobbs Time UNKNOWN

Propeller Time Since Overhaul -0-

COMPLETELY OVERHAULED PROPELLER ASSEMBLY IN ACCORDANCE WITH HARTZELL SERVICE MANUAL #117D.


COMPLIED WITH SERVICE LETTERS 177,61T,69,82A,101A,148A,154,155A.

COMPLIED WITH SERVICE BULLETINS 118D,136H,142B,159A,213,224R2,224R1.

COMPLIED WITH A.D. NOTES 71-21-09,77-12-06

Work Performed By Tiffin Aire Inc.

Repair Station #IC5R930M. Work Order/Invoice # 13268

Signature  BND.


# MAINTENANCE & SERVICE HISTORY

Date Total

Date 09/24/97

Propeller Total Time UNKNOWN

Tach/Hobbs Time UNKNOWN

Propeller Time Since Overhaul 0.0

INSTALLED 2 NEW B.F.G. 4E1188-3 DE-ICERS IN ACCORDANCE  
WITH HARTZELL ALUMINUM BLADE OVERHAUL MANUAL #133C.  
INSTALLED 2 NEW TY527M TY-RAPS AND 1 NEW CAU113 DECAL.

Work Performed By Tiffin Aire Inc.

Repair Station #IC5R930M. Work Order/Invoice # \_\_\_\_\_

Signature

*[Handwritten Signature]* **SEND.**



# MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
4/2/99	1268.8 Hobs	198.0 Hrs.	Serviced propeller w/ Aeroshell 6 grease. I certify that this aircraft propeller has been inspected TAW. <del>ATW</del> annual inspection and was determined to be in air worthy condition. No leaks noted at this time. END.	Gregory S. Shaw ATP 28274266IA.
2/11/00	1472.6 A/C HBBs		C/W Annual Ins. Greased & lubed <del>Reduction</del> AJVR135C	

