




LEFT ENGINE

FACTORY
REBUILT 6
ENGINE LOG

N 688AC

SERIAL NO. TE-262

 TELEDYNE CONTINENTAL MOTORS

LEFT

This engine model T0520C7, serial No. 238978A,
has been rebuilt by Teledyne Continental Motors. All applicable
Federal Aviation Administration regulations and mandatory Teledyne
Continental bulletins have been complied with. This log book shall
indicate zero hours.

By

[Signature]

Date

11-14-80

 **TELEDYNE CONTINENTAL MOTORS**
Aircraft Products Division

ENGINE DESCRIPTION

*installed
3504 3/23/81*

DATE _____ MODEL _____ SERIAL NO. _____

RATED H.P. _____ MAXIMUM H.P. _____

RATED R.P.M. _____ MAXIMUM R.P.M. _____ OIL PRESSURE _____

BORE _____ STROKE _____ DISPLACEMENT _____ CU. IN. _____

COMPRESSION RATIO _____ GEAR RATIO _____

PROPELLER _____ HUB DESIGN _____ HUB SERIAL NO. _____

BLADE DESIGN _____ BLADE SERIAL NO. _____ BLADE SERIAL NO. _____

MAXIMUM HUB H.P. _____ MAXIMUM BLADE H.P. _____

PITCH _____ DIAMETER _____ LENGTH _____

OWNERS NAME _____

ADDRESS _____ CITY _____ STATE _____

