

AIRCRAFT LOG
AF5-1

MAINTENANCE RECORD

F.A.R. 43.9

THIS LOG STARTS 5-1-2002

DESCRIPTION OF WORK PERFORMED
OR APPROVED DATA USED

AGENCY & CERTIFICATE NO.
WORK PERFORMED/RETURNED TO SERVICE

DATE OF
COMPLETION

AIRCRAFT TIME
IN SERVICE

5/1/2002

3092.4

TACH & TAT. THE FOLLOWING WORK WAS

PERFORMED.

① Aircraft was disassembled (wings-engine, tail section) and transported from Wale Field Airport to Olympia City Airport (1G1) for purposes of reconstruction, annual inspection and engine major O/H.

② Removed Lt & Rt Fuel tanks. - R/H Cell, Cleaned, Tested & recertified SN 1737. Lt tank replaced with SN CR2546, New.

③ Removed & replaced Battery with new serviceable unit. SN G01996340

④ R/R Vacuum Regulator.

⑤ R/R Battery & Starter Solenoid.

⑥ Installed Avionics - King Mod. AK-450 EHT Battery next due @

⑦ Vort. Speed Ind, Airspeed Ind, Altimeter were O/H.

⑧ Removed old, excess wiring from instrument panel

⑨ Reassembled Aircraft (wings, tail & rigged IAW the Lesma Aircraft Service instruction.

⑩ Removed & replaced all plexiglass windows & windshield.

⑪ Installed Overhauled engine Continental 0470R SN 133126-b-R

(See engine log for O/H details.

CONT. →

