TELEDYNE CONTINENTAL




Gold Medallion Aircraft Engine


REBUILT ENGINE LOG

N4382A

AIRCRAFT N NUMBER



ENGINE MODEL NUMBER



ENGINE SERIAL NUMBER

Gold Medallion® Warranty protection

All Teledyne Continental Motors engines delivered as original equipment after January 1, 1980 are protected by TCM's exclusive Gold Medallion Warranty. This new warranty provides extended protection to the TBO of your engine. See your TCM distributor for all the facts or write direct to Teledyne Continental Motors for a free brochure.

Service Information

Service Bulletins and Technical Publications are available on a direct mail basis from the factory. Orders must be prepaid. Send for order form or call (205) 438-3411, publications department, for information.

** TELEDYNE CONTINENTAL MOTORS
Aircraft Products Division

P. O. Box 90 . Mobile, Alabama 36601

This engine model 10550 B4F, Serial No. 2492/6-R, was rebuilt on 2/2/89 by Teledyne Continental Motors in accordance with approved design data and the applicable requirements of Part 21 of the Federal Aviation Regulations. The approved design data for this engine incorporates all changes required by applicable Airworthiness Directives and Teledyne Continental Motors Service Bulletins.

TELEDYNE CONTINENTAL MOTORS

TELEDYNE CONTINENTAL MOTORS
Aircraft Products Division

ENGINE DESCRIPTION

TYPE_TCM	MODEL 10-550-B	SERIAL NO. 249216-R
RATED H.P.		
RATED R.P.M.	MAXIMUM R.P.M.	OIL PRESSURE
BORE	STROKE	DISPLACEMENT CU. IN
COMPRESSION RATIO		GEAR RATIO
ROPELLER	HUB DESIGN	HUB SERIAL NO.
ADE DESIGN	BLADE SERIAL NO.	BLADE SERIAL NO.
AXIMUM HUB H.P.	MAXIMUM BLADE H.P.	
тсн	DIAMETER	LENGTH
WINERS NAME DAVID	J. FRIIS	
		STATE AK 99516

DATE	R.P.	м.		ME O			TIME I	N	TOTAL	TIME	REPAIRS - ADJUSTMENTS	SIGNATURE	LICENSE
DATE	Ground	Air	Hrs.	Min.	Total	Hrs.	Min.	Total	Hrs.	Min.	REPAIRS ASSOCIATION		NUMBER
7/19/89									-0-		INSTALLED Parting A	etalt Co	nomenta
7.6					3-10		100	10 to 10	STALL ST		114 (1 1 101/10) 12 - 12 4 6	5BN 43	82A
			- 10			7		1111111		1.86		INNON ATE	QUETS.
						AK	1701	41 Tine	= 380	3.49	STC SAZZOOSW L	Deight as	1.
			-			1	70	1 1-5			balance competed a	is of you	D CHATE,
			2			-/-		1-12		1	and complet 115T in	ised.	
	10	te:	Yeur	00	ed	1/05	17.0	talac	poice	K	The state of the s	1 10 10 10	
	-)r-10	in:	No	04)	ust	y Cle	0016	1	1	14328	48/10	
		94	ake	20	00	RIA	10	w to	16.70	10100	- acceptly///	1//	100
					70000						Y Delash	delen	
		200					45	100	1000				
			15 33	-	100			1.3	and the		ACCEERS		
											TRANSPART :	ULFO	
											MORNO ENERGY DISC		
	التاسا												
BROUGE	HT FORWA	ARD					-			-			
	TOTAL	\$									Marie Control		

DATE	R.P.	.м.		IME O			TIME II	N	TOTAL	TIME	REPAIRS - ADJUSTMENTS SIGNATURE LICEN
	Ground	Air		100000	Total	Hrs.	Min.	Total	Hrs.	Min.	NUM
PERSONAL SECTION AND SECTION A	ENENT DE	TALLS OF A	THE RECORDER IN	AC DEP	PESENTA	LE AT TELEVISION	TO OT		Tr. Pr	rgine op fima thro en c.e.	3834.99 31.46 SMOH 79.80 SOH 2003.32 5614.89-19 1078 AIRCRAFT 1.501-38 A/F-1-3
500 6	anurar)				CATE NO				CHAN		OIL HOST MUSIL ONE
		BUD'	S AIRC	RAF	r .	3	-		CHAN	980	OIL PLIER CH48109
			ngs, Ales		M	- 7	ıåı				
ROUGHT	FORWAR	D									

DATE	R.P.	.м.		ME O			TIME I	N	TOTAL	TIME	REPAIRS - ADJUSTMENTS	SIGNATURE	LICENSE
DATE	Ground	Air	Hrs.	Min.	Total	Hrs.	Min.	Total	Hrs.	Min.			NUMBER
#18/41	TAKA COMP	3060 CHE						74 A	# 74 1891	CERT HAS ACCO	TUTER CHARACTER TO THE THIS STATE OF THE THIS STATE OF THE THIS STATE OF THE THE THIS STATE OF THE THI	WAY .	1 C N
								0010	Xunvall	CONE	ITION. D. GLUECK ASP/FM/798364		
BROUGI	TOTAL	_									der ball	4 10	

DATE	R.P.	м.		IME O			TIME I	N	TOTAL	TIME	REPAIRS - ADJUSTMENTS	SIGNATURE	LICENSE
DATE	Ground	Air	Hrs.	Min.	Total	Hrs.	Min.	Total	Hrs.	Min.			NUMBER
inspe inspe sirwe W.O.	rtify to cted in ction a rthy co	according was nditto	dance deter DA AIRCR	with mined TE_ AFT M KA 9	4-22-	in T	ch D's	ngine rop Time Thro	5 AJA	3. S.	5mold #1 70/80 #2 5mold #4 12/80 #2 50H 12/5/B 2438 07 Gillelled exhau 07 (4) Replaced oil 57 Changed Od 501 (6) Checked may tim (1) Jasp cleaned +50 (8) displaced air fulte	ilter +80th Als 1550 ing OK	OK.
BROUGH	T FORWAR	RD											

DATE	R.P	м.		ROUN			TIME II	N	TOTAL	TIME	REPAIRS - ADJUSTMENTS	SIGNATURE	LICENSE
2011	Ground	Air	Hrs.	Min.	Total	Hrs.	Min.	Total	Hrs.	Min.			NUMBER
8-8-9	2	TACH	1.21	80.	4	W.0	# 94	38					
	1210	esla	ed C	rock	ker (15-5	00	cony	on H	2 o	#4 Cegl.	Her State of	
	SI W	glac	od Or	1 1	P.	dis 1	W d	elters) (14T) 1		TOTAL TRANSPORTER	1712-000	
					ANCHO	MAGE,	MARK	A#-1-			STUTE OF STUTEN R. HALL T.A. SIISSSESI	Colo Mileson	
										10W			
BROUGH	IT FORWA	RD						H					
	TOTAL	ŝ											

DATE	R.P	.м.		ROUN			TIME I	N	TOTAL	TIME	REPAIRS - ADJUSTMENTS	SIGNATURE	LICENSE
DAIL	Ground	Air	Hrs.	Min.	Total	Hrs.	Min.	Total	Hrs.	Min.		SICIANIORE	NUMB
26/93	2227	17%	CH	23	5.29	-77	# 7	504	001	ALI	TER LIMINE INSAE	cotion A	1000
	500	16 3	De	700	6 00	Enn	40	1200	0. 3		when out ou fic		2010
	wit	ed s	Sugra	Spel	wer	250	50	-	-p 4.	7	5-74-75-70-74-75	40 HH	246
	0001	و نا	GAN	D	LUG	V	-/2	w 7	cm (11/13	193-9 REALINES	FUELD	220
3	004/	6.00	C	20	DUA	ces	120	HER	COUE	er !	assilets RER AN	J. L. 57.	16
	in	1.11	is	sei	- R.	econ.	05	6	20000	124	~ CK OK		
	T CPD	PIPY	HAT !	THE	. 15	46.	100	HAC DE	EN INS	PPM	PED TN		
	ACCOR	SALVOR	WIT	4		ACUL		TESP	C PECIN		WAS		
	DETER		TO B	E IN	AIR	POTON		DITTO	W.	-10	SALMOTERS . S. R.D.		
			1		TEVE	IR. H	ALL			10001	AND THE PARTY OF T		
	5	2/4	Sele	_ 1	.A.	11566	463						
			-1-					W/0	1 35	B			
Maria	-13	non	CM	20	AVI	47200		-	"				
		-		_									
BROUGH													
	TOTALS				-					9			

DATE	R.P	P.M.		TIME OF			TIME II	7	TOTAL	TIME	REPAIRS - ADJUSTMENTS SIGNATURE LICENSE
93	Ground	Air	Hrs.	Min.	. Total	Hrs.	Min.	Total	Hrs.	Min.	NIIMREP
9-1-	Tas	eh,	226	218	\$7	111					hange O & filly ebs Down
										En	and the second second
						-				/	Moberto Brungerd
											1414806791
may II	85 700	PH TE	n5 !	128	23	REP	100	FO F	DYEN	D	ZURN URGUM PUMP
"						-	Research	w.ltd. The	DA IVE	V	two Cultill Dis PSTAD A FALCY
						119					- Thanker 11 sour 141
FEB 2	I TA	10H 70	ME 3	30	88	RICE	NAME OF TAXABLE PARTY.				DORNATHERM WASHED & ROW EVE
						LEDI	K.C	K OK	two	04/10	AL ASP 502024929
2 10	1 4			12/		Alm			1/2	-	6.3050 ft 2.3050
LMAY9	4 14	CH 7	MES	15/4	7.3	CHAP	MARI	2 08	THE F		
						SPICE	LEE	PHEI			NEIL ISWSO, CLEANED & GOPPED SPACK PLUC
						199-11	IC				O CHRKED COMPRESSION & MRK TEMING B.D. WAS PERUTOUSLY COMPRESED WITH BY COMP
						1077	AFT	MY M	KB. M	19329	
BROUGH	HT FORWAR	RD							And the second		Charles Co. Salk Trees 14
	TOTALS	5									THE RESERVE OF THE PARTY OF THE

DATE	R.P.	м.		ROUN			AIR	N	TOTAL	TIME	REPAIRS - ADJUSTMENTS SIGNATURE LICENSE
DAIL	Ground	Air	Hrs.	Min.	Total	Hrs.	Min.	Total	Hrs.	Min.	NUMBER
5-2-99			0	cer	tipes	th	10	ene	ine -	has	been inspected in accordance
			con	th	de	6	ns	wal	ins	pac	tion and was determined to be
_	46.00		de	0	risi	rost	ly	con	NAME OF TAXABLE		Dona al E. Low 14 1943857
24/45	_	15106		-1	1567	BLLE	11	264	TACA	a	CABING -4251 - Specientif 24564
- 7-95	9275	O TA			The second second	06 31					Eleren service con become
			15	Lund	50	620	العرف	Pus	CFO	-	ORAJO AIP 511566963
11/20	4294	2 -4	~ 11	49	od	77	- 1	-	2 01	-	a Annua INSP. AS DER SEARE &
170	76 070	13. 173					No. of Concession,	A NAR		-	E SIL & OLEN OIL PLACE SERVI
			en 17		1/0		-/	- Andrewson		1	-75 -77-72-78-60/00 moran
			ALL	N	Ew	SPA	RE	الند و الدوا			BEE REPLACE AND KICKER
			%	10	78-	59-0					we can printe map & pen /8 5992
	MI	CSTX	NE	4	000	479	4,3	1100	nsch!	6	resumment of CK BOSK CK. O
	EAR	Clo	(12)	2.5	2007	CERTI	Y T	HAT T	IS E	10	HAS BEEN INSPECTED IN
				A.Kin	AC	CORDAL	VCE	WITH	A	ALL	UK INSPECTION AND WAS
					DE	PERMIT		IN BE	TN AT	MOS.	HY CONDITION.
BROUGH	TOTALS			10	AW 6	12	Ja.	ge_	I.A.		66463

BRUNGARA ANATON

W/014057

	R.P.	.м.		IME O			TIME I	N	TOTAL	TIME	REPAIRS - ADJUSTMENTS	SIGNATURE	LICENS
DATE	Ground	Air	Hrs.	Min.	Total	Hrs.	Min.	Total	Hrs.	Min.			NUMBE
9-27-96	4323	3 7		7/4	~ /	460 500 86	-	311	TECS	151		2/2000	4-
11/1/96	4342			50	rusc	5	É	And I	21	4/2	TUTGGGG	ck of	
/20/97	F BACCE	50- 10 10 10 10 10 10 10 10 10 10 10 10 10	Sec.	er.	Ser	CONTRACT AC	CERT	THE A	10/0	IS &	AVALUATION TO THE SECONDA AND THE SECONDA AND THE PROPERTION TO RESTRICT TO THE PROPERTION OF THE PROPERTION OF THE PROPERTION OF THE PROPERTION OF THE PROPERTIES OF THE PROP	JCK O	AIL OIL
DROUGHI	TOTALS						EBR	BELL	A.I		W/O#		

DATE	R.P.	м.	700	ME O			AIR	N	TOTAL	TIME	REPAIRS - ADJUSTMENTS	SIGNATURE	LICENSE
DATE	Ground	Air	Hrs.	Min.	Total	Hrs.	Min.	Total	Hrs.	Min.			11011021
10/28/97	443	1.4	TACA		CHA	NGE	0 8	en t	CLE	1	care Have on fire	v.	
			SER	VIC	10	LATA	1	40	150	50.	Granapia CKO	<i>C</i>	
						5/	21	fall	AH		57×66463		
				1		4		H.			and desired	4	
1498	4471=	7/30	41 -	6	0/.3	-4-4-0	8	- Come	200	-	compicies AND	Se const	-
				000	500	5/10	40	DOTA	30	7	46 7 168 74-72	capi	1465
		بلياتي	OR	100		5 -		1	CIC;	10	66 74-68-79-72	Bere	
			016								REPLACE BLACKET A		
-			. 10-	63	100	2000	100	CU	121	TE	2 51237-8. Gran	O LUNC	K 01
_			-	PROP	TEV	STATE T	HIB	FN	ing	HAS	BEEN INSPECTED IN		
			THE REAL PROPERTY.	-	ANCE				NUNC		SPECTION AND WAS		
			DE	TER	KINED	TO B	IN	AIRW	RTHY	COND	TION.		
				5	001	1	9	TEVEN	R. HA	L	Brun GARA AVERT	00	
-				0	126		1	.A. 5	115664	63	Bourpor Cs.		
BROUG	HT FORWA	ARD						100		1	and the same of th		
	TOTAL	5		-	100	L. C. Land	LITE		1200				

ENGINE LOG

LICENSE	NUMBER	朝川			
SIGNATURE		Scoot of the se	S of the Sold of t		
REPAIRS - ADJUSTMENTS	00	Salso uplus	A Line Man Comment of the Comment of	RTD. BRUNGARD	Cincon
TOTAL TIME	Hrs. Min.			OBERT IA 1	ı
	Total		The same	102	
TIME IN	Min.		3 1/43 3		ı
	Hrs.		\$ 5 5 3 B		ı
TIME ON GROUND	Hrs. Min. Total	672	A Property of	1	
TI	Hrs.	50	2 2	-	ı
7	Air	8	<u> </u>		
R.P.M.	Ground		3/2	BROUGHT FORWARD TOTALS	
-	300	20	36	BROUGHT	

ENGINE LOG

LICENSE	NUMBER		
SIGNATURE	1	The state of the s	
PEDAIDS - AD HISTMENTS		Stoller Row Burner Hall Brund	
TOTAL TIME	Min.	30 300	
TOTA	É	Security III	
	Total	00 120	
TIME IN	Min.	N 10 3	
	Hrs.	NO	
ZΩ	Hrs. Min. Total	7 6 6 7	
TIME ON GROUND	Min.	7 7 7	
	Hrs.	3 9 1300	
M.	Air	26 2 25	S S
R.P.M.	Ground	n of B	T FORWAR TOTALS
	OPE OPE OPE OPE OPE OPE OPE OPE OPE OPE		BROUGHT FORWARD TOTALS

ENGINE LOG

	NUMBER	MSZROIGE	8	Street Street	Ver Line
SIGNATURE		A CRS	3	1323	920
REPAIRS - ADJUSTMENTS.		Month of the office # 5	Will new - 1348	Lace Interest	of Solo Solo
TOTAL TIME	Hrs. Min.	dately	moste	334	May the
TIME IN AIR	Hrs. Min. Total	L. M. J.	5 Ethni	The same of the sa	The total
TIME ON GROUND	Hrs. Min. Total H	orth Clean	effore #5	4730.58	701
R.P.M.	Ground Air	468.2491	00	CO Teach	BROUGHI FORWARD TOTALS
	DAIE	23	25.07.6	71-12	вкоиснт

R.P.	R.P.M.						TIME IN AIR			TOTAL	TIME	REPAIRS - ADJUSTMENTS SIGNATURE LICEN
Ground	Air	Hrs.	Min.	Total	Hrs.		Total	Hrs.	Min.			
4742	778	1.90	19.2	TT.	CH	121	EE DI	c of 0	14	TER, SERVICE OF EXX 25 25000,		
		city	000	SAA &		- 1	2460	C 6	- War	CK: 79-70-75-14-16-17-00		
					me	THOT	2	CLEN	ins de	VEL NOZZCEJ GRAVNA RUN		
	S.E.I.	che	CK	ok.				The second second	100000000000000000000000000000000000000	AL INSPECTION AS PER SCOPE AND		
	1000	1		-014	61	1619	STREET, SQUARE,	S STATE OF THE PERSON NAMED IN		SEEN INSPECTED IN ACCORDANCE WITH		
	H. A.	2.5.3		Harry 1	177	richte				INSPECTION AND WAS DETERMINED TO		
								The state of the s		CONDITION. REF. LISTING OF A.D.'S IN		
	7.00						MITTE			BRUNGARD AVIATION LLC		
								PM	AV-	BOULDER, CO		
								TA	711	566463		
111-	01	1.17	74	184	0	20	wo	0	0	leller Egypy 2010-50		
19		77	-				1	Re	C	D. Bridge		
								141	1	1148007		
	Ground FM2	Ground Air	R.P.M. Ground Air Hrs. HMZ 1711-11-90 CLES PAP CHE TFORWARD	R.P.M. GROUN Ground Air Hrs. Min. HMZ 7 TA 1. 93 9 2 CLEW G REPLAN CHECK TFORWARD	Ground Air Hrs. Min. Total HAZ TTAN 9892 TT. CLEAN GAPP REPLACE OK.	GROUND GROUND GROUND GROUND GROUND Hrs. Min. Total Hrs. FMZ 7714.939277. CH. CLEAN CAAR TEGO PEACE AIR CAAR CHECK OK.	GROUND AIR GROUND AIR GROUND AIR GROUND AIR GROUND AIR GROUND AIR Hrs. Min. Total Hrs. Min. FM2 7 TA N. 98 9 2 TT. CHAN CLEAN GAST TEXT A REPLACE OK. GROUND TFORWARD	GROUND AIR GROUND AIR GROUND AIR GROUND Hrs. Min. Total Hrs. Min. Tota	GROUND AIR HOTAL GROUND AIR HOTAL GROUND AIR HOTAL GROUND Hrs. Min. Total Hrs. Min. Total Hrs. Hrs. Min. Total Hrs. Min. Total Hrs. CLEAN GARTTEON ACCUSE CHARLETED DETAIL OF CHARLETED DETAIL OF AIRCRAFT RE AIRCRAFT RE TA	Ground Air Hrs. Min. Total Hrs. Min. Total Hrs. Min. THE TIME PROPERTY CHANGE OF A CONTRICTED ANNUAL DETAIL OF FAR. HAS A ALVANDAL HAS A STANDAL HAS A STA		

DATE	R.P.	.м.	BRUNGARD AVIATION	SIGNATURE	LICENSE
PAIL	Ground	Air	BOULDER, CO		NUMBER
			7-01-2002 4807.3 TT N35M TCM IIO550-R4F S/N 249216-R 1003.8 TT		
			CHANGE OIL AND OIL FILTER, REFILL WITH EXXON 20W50 CLEAN GAP		
			« TEST PLUGS, COMP CHK; 74-64-70-70-74-72/80 INSTALL NEW ΔIR		
			FILTER ELEMENT, C/W AD 96-12-07 MAG IMPULSE COULPLING INSP. GROUND RUN CHK OK.		
			COMPLETED ANNUAL INSPECTION AS PEN SOUTE		
			Dayin, of July 10 Parts of 1 Control of 1	THIS	
		200	ENGINERAS BEEN INSPECTED IN ACCORDANCE		
		0703	A A PROPERTY ON A PROPERTY ON A PROPERTY OF A DETERMINED OF A	the latest	
-	_	ni e s	A 40 DATE SU A STANGE OF ALCE AND	. S IN	-
-		200, 74 10		LLC	
		235	BOULDEN CO		
			00 H 1 H 1 T 1 T 1 T 1 T 1 T 1 T 1 T 1 T 1		
7-7	3-07	100	Tack 4943,77 . h. 1.	1 20 10	
200			River VI & filter Eyfon 2000 50	1	
			grande a grandi of a color		
			hely Bruged		
			110000000000000000000000000000000000000		
BROUGHT	FORWAR	RD	187989677		
	TOTALS				

DATE	R.P.M. Ground A	BRUNGARD AVIATION BOULDER, CO 7-18-2003 4857.3 TACH 1053.8 TT N35M TCM 10550-B4F COMPLETED ANNUAL INSPECTION; CHANGE OIL & OIL FILTER, REFILL WITH EXXON 20W50, COMP CK; 76-70-72-74-76-74/80, CLEAN GAP AND TEST PLUGS. INSTALL NEW AIR FILTER ELEMENT. GROUND RUN OK. COMPLETED ANNUAL INSPECTION AS PER SCOPE AND DETAIL OF FAR 43 APP. D. I CERTIFY THAT THIS DETAIL OF FAR 43 APP. D. I CERTIFY THAT THIS INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. REF. LISTING OF A.D.'S IN AIRCRAFT RECORDS FOR DETAILS. BRUNGARD AVIATION LLC BOULDER, CO	SIGNATURE	LICENSE NUMBER
		SE IN ARTICHINY CONTINUE REPORT OF AREA IN ARTICHING AND A		
BROU	GHT FORWARD TOTALS			

DATE	R.P.M.		BRUNGARD AVIATION NTS	SIGNATURE	LICENSE
DATE	Ground	BRUNGARD AVIATION BOULDER, CO 7-20-2004 4904.4 TACH 1100.9 TT N35M TCM IO550-B4F COMPLETED ANNUAL INSPECTION; CHANGE OIL AND OIL FILTER, REFILL WITH EXXON 20W50. COMP CHECK; 74-60-70-65- 70-70/80. INSTALL NEW SPARK PLUGS WITH NEW SLICK MAGS AND HARNESS ASSEMBLY. R & I #6 CYLINDER FOR REPLACEMENT OF EXHAUST STUDS, NEW GUIDES AND RINGS. REF MAINT RELEASE FROM AIRCRAFT CYLINDERS. ALTERNATOR REMOVED FOR INSPECTION. LEFT EXHAUST STACK O'HAULED BY DAWLEY AVIATION. CLEAN FUEL SCREEN AT FUEL SERVO. INSTALLED NEW BRACKET AIR FILTER. GROUND RUN CHECK OK. COMPLETED ANNUAL INSPECTION AS PER SCOP DETAIL OF FAR 43 APP. D. I CERTIFY THAT WARD BE IN AIRWORTHY CONDITION. REF. LISTING OF A AIRCRAFT RECORDS FOR DETAILS. BRUNGARD AVIATIC BOULDER, CO	SIGNATURE	NUMBER	
			TAT 10 66963		
BROUGH	T FORWAR	D			
	TOTALS				

DATE	R.P.	M.		SIGNATURE	LICENSE
	Ground	Air	BRUNGARD AVIATION BOULDER, COLORADO 7-05-2005 4955.8 TACH 1152.3 TSOH N35M TCM IO550-B4F	SIGNATORE	NUMBER
			COMPLETED ANNUAL INSPECTION; CHANGE OIL AND OIL FILTER, REFILL WITH EXXON 20W50. CLEAN GAP AND CHECK PLUGS, COMP CHECK; 70-64-70-66-70-74/80. R&I # 5 CYLINDER FOR OVERHAUL BY GIBSON AVIATION, REF MAINT RELEASE. REINSTALLED WITH NEW RINGS AND SEALS. RIGHT EXHAUST MANIFOLD REPLACED WITH NEW PART FROM KNISLEY WELDING. INSTALLED NEW BRACKET AIR FILTER ELEMENT. GROUND RUN CHECK OK.		
			COMPLETED ANNUAL INSPECTION AS PER SCORE DETAIL OF FAR 43 APP. D. I CERTIFY THAT CHAS HEEN INSPECTION AND WAS DETERMINE INSPECTION AND WAS DETERMINE BE IN AIRWORTHY CONDITION. REF. LISTING OF A.S AIRCRAFT RECORDS FOR DETAILS. BRUNGARD AVIATION BOULDER, CO	SO TO O'S IN	
			115/1566463		
ROUGH	T FORWAR	D			9

DATE	R.P.	R.P.M.		BRUNGARD AVIATION BOULDER, COLORADO SIC	GNATURE	LICENSI
	Ground	Air	Hrs	8-08-2006 5003.4 TACH 1199.9 TSOH N35M TCM IO-550-B4F		NUMBE
				COMPLETED ANNUAL INSPECTION; CHANGE OIL AND OIL FILTER. REFILL WITH EXXON 20W50. CLEAN, GAP AND CHECK PLUGS COMP CHECK; 70-60-70-74-75-72/80. INSTALLED NEW BRACKET AIR FILTER. GROUND RUN CHECK OK.		
				COMPLETED ANNUAL INSPECTION AS PER SCOPE AND DETAIL OF FAR 43 APP. D. I CERTIFY THAT THIS DETAIL OF FAR 43 APP. D. I CERTIFY THAT THE THAT THE THIS DETAIL OF FAR 43 APP. D. I CERTIFY THAT THIS DETAIL OF FAR 43 APP. D. I CERTIFY THAT THE		
				AIRCRAFT RECORDS FOR DETAILS. BRUNGARD AVIATION LLC BOULDER, CO		
			Di Taki			
			that if			
BROUGH	T FORWAR	RD D				
	TOTALS					

DATE	R.	BRUNGARD AVIATION BOULDER, COLORADO	ENTS	SIGNATURE	LICENSE
	Groun	9-01-2007 5009.1 TACH 1205.6 TSOH N35M TSIO 520B4F			
		COMPLETED ANNUAL INSPECTION; CHANGE OIL AND OIL FILTER, REFILL WITH EXXON 20W50. CHECK COMPRESSION AND INSPECT PLUGS. GROUND RUN CHECK OK.			
		COMPLETED ANNUAL INSPECTION AS PER SCOPE AND DETAIL OF FAR 43 APP. D. I CERTIFY THAT THIS DETAIL OF FAR 43 APP. D. I CERTIFY THAT THIS DETAIL OF ALL STIME OF ALL			
		AIRCRAFT RECORDS FOR DETAILS BRUNGARD AVIATION LLC			
		17756463			
ROUGH	T FORWAR	D			

	R.P.M.		TIME ON GROUND			TIME IN AIR			TIME	REPAIRS - ADJUSTMENTS	SIGNATURE	LICENSE	
DATE 10-6	Ground	Air	Hrs.	Min.	Total	Hrs.	Min.	Total	Hrs.	Min.			
200		Toec	R 5	0	24.6	5	Ct	ange	Oi	18	liller Espen 20-	50 nec	·
-				1	Cirl	ente	asi (West	lifter	Co	Jessey 74, 56,72	,70,76	.72
				ch	ch,	my	in	or C	Jan,	Cog	1 Rotate flags		
						/		The state of the s	Eng	/	has been inspected in accord-		
								certify the	Cart	1	inspection and determined to		
									thy come	3	1		
						Surrein	INC.	DA ST	Beli	100	B. and		
						Set Made	1 100	Signed ,	DODE	DID	OW/NOADD		
								-	HUBE	IKI U	20679 HARDINA		
					24	HOITA	VEC	Flagani	1923	A 14	80679 H LARENCA		
						00.5	HOL	DOB.					100
	-												
										+			
BROUGH	IT FORWA	RD											
3.0001	TOTAL												

	2101112 200			
DATE Gro	BRUNGARD AVIATION BOULDER, COLORADO 11-6-2009 5043.5 TACH 1240.0 TSOH N35M ENGINE LOG	5 510	SNATURE	LICENSE
	COMPLETED ANNUAL INSPECTION; CHANGE OIL AND OIL FILTER, REFILL WITH EXXON 20W50. COMP CHECK; 74-64-74-70-74-76/80. INSPECT PLUGS. CHECK TIMING AND RESET RIGHT MAG TIMING. GROUND RUN CHECK OK.			
	COMPLETED ANNUAL INSPECTION AS PER DETAIL OF FAR 43 APP. D. I CERTIFY CHAS BEEN DISPECTED IN ACCORDING TO AN ANOMAL DE IN AIRWORTHY CONDITION. REF. LISTING AIRCRAFT RECORDS FOR DETAILS.	THAT THE ROANGE HITH TERMINED TO LOF A.D. S IN		
	BOULD BOULD	المناه بالأشاشان أرافا		
BROUGHT FORWA	(ARD			
TOTAL	LS S S S S S S S S S S S S S S S S S S			

DATE	R.P.M.	TIME ON GROUND	TIME IN AIR	TOTAL TIME	REPAIRS - ADJUSTMENTS	SIGNATURE	LICENS
DATE	Gri E	RUNGARI	AVIATIO	V BOULDE	R, COLORADO		
	12-1	4-2010 5052.8	TACH 1249.3	TSOH N35N	N ENGINE LOG		
	WITH E	EXXON 20W50.		74-70-74-74/80.	OIL FILTER, REFILL CLEAN GAP AND IN CK OK		
		DAYA.	HAS BEEN	APP. D. I C NINSPECTED IN RECTION AND 1	PER SCORE SIZE ENTIFY THAT THIS ACCORDANCE WITH AS DETERMINED TO		
		Ainci	AFT RECORDS FO	F DETAILS.	ISTING OF A.D.'S IN		
			-A3435	577			
ROUGHT	T FORWARD						
	TOTALS						

ENGINE LOG

	500		H	1.1				1.1		1.1	1	1
	ROUGH									1-2		DATE
TOTALS	BROUGHT FORWARD									173-2	Ground	R.P.M.
	õ									012	Air	.M.
										7	Hrs.	0 1
										10	Hrs. Min. Total	TIME ON GROUND
										50	Total	02
						2				R 5077.5	玉.	
						A. W.	58			7	Min.	TIME IN AIR
						the	The second			Smok	Total	
			Signed	be in a	leos!	1	がか	発起	2-2	127	Hrs.	TOTAL TIME
			W.	inworth	this d		Tie	25	in	D. L.	Min.	TIME
		IA 1480679	of the burney	be in sinvoidity condition	Small Borness		The Real of	w KT and market	unery filtely take	Must will the		REPAIRS - AD ILISTMENTS
				med to		01	no forte	and of	te al	Otes The		SIGNATURE
						0	Chy.	risley	inela	inc	NUMBER	LICENSE

DATE	R.P.M.	TIME ON GROUND	TIME IN AIR	TOTAL TIME	REPAIRS - ADJUSTMENTS	SIGNATURE	LICENS
	E	BRUNGARI -12-2013 5085.3	TACH 1281.8 TS	N BOULDER OH N35M ENGIR	R, COLORADO		
	REFILL TIMING RECOR	WITH EXXON 2 G. GROUND RUI RDS. C/W INSP ERTIFY THAT TH	ECTION AS PER	(72-60-74-64-72 EF LISTING OF SCOPE AND DE HAS BEEN INS	-70/80. CHECK AD'S IN AIRCRAFT ETAIL OF FAR APP.		
_	TOPE	IN AIRWORTHY	CONDITION. ST	EVEN R HALL IA	3435597		
	1062	III AII CONTIN		te Re Vo	le -		
	TOBE			the K	le -		
	TOBE			Ster V	le -		
	TOBE			the No	le -		
	TOBE			the No	le -		
SROUGHT F				the No	le -		

DATE	R.P.M.	TIME ON GROUND	TIME IN AIR	TOTAL TIME	REPAIRS - ADJUSTMENTS	SIGNATURE	LICENS
		RUNGARD			COLORADO		
		1-2014 5103.8 TA					
	COMPET EXXON 2	ED ANNUAL INSPE	ECTION; CHANGE (OIL AND OIL FILTI	ER, REFILL WITH		
-	_ GROUND	RUN CHECK OK	REF LISTING OF	AD'S IN AIRCRAF	TRECORDS CAN		
	ENGINE	HAS BEEN INSPEC	TED IN ACCORDA	NCE WITH AN AN	ERTIFY THAT THIS NUAL INSPECTION		
	- AND WAS - 3435597	S DETERMINED TO	BE IN AIRWORTH	Y CONDITION. S	TEVEN R HALL IA		
		SPI	10		# <u></u>		
		SAI	10				
ROUGHT	FORWARD						

DATE	R.P.M.	TIME ON TIME IN		LICENS
DATE	Ground A	BRUNGARD AVIATION BOULDER, COLORADO 4-16-2015 5109.4 TACH 1301.4 TSOH N35M ENGINE LOG ENTR	SIGNATURE Y	NUMBER
		COMPETED ANNUAL INSPECTION; CHANGE OIL AND OIL FILTER, REFILL W EXXON 20W50. COMP CK 76-60-74-64-76-74/80. GROUND RUN CHECK OK. LISTING OF AD'S IN AIRCRAFT RECORDS. CM INSPECTION AS PER SCOFF AND DETAIL OF FAR 43 APP. D. I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND FOUND IN AIRWORTHY CONDITION. STEVEN R HALL IA 3435597	REF	

DAT	BRUNGARD AVIATION BOULDER, COLORADO 5-12-2016 5144.0 TACH 1336.0 TSOH N35M ENGINE LOG ENTRY									SIGNATURE	LICENSE
	CHECK TII RECORDS CERTIFY T ANNUAL IN	W50, CC MING, GR CW III HAT THI NSPECTION	OMP CK; 70 ROUND RUNSPECTION S ENGINE ON AND FOR 3435597	D-62-72-64-7 JN CHECK ON AS PER S HAS BEEN OUND TO B	5-70/80. (OK. REF SCOPE AN INSPECT IE IN AIRV	CLEAN GA LISTING C ND DETAIL ED IN AC	FILTER; REI AP & TEST P AP AD'S IN A COF FAR 43 CORDANCE CONDITION.	LUGS. RCRAFT APP. D. 1			
											FILE
-											
	T FORWARD										

	R.P.M.		TIME ON THE IN		LICENS
DATE	Ground	Air			
			BRUNGARD	Engine Logbook Entry AIRCRAFT N35M	
			AVIATION, LLC	7-19-17	
			TACH TIME 5198.85 HRS.	ENGINE TSMOH 1388.8.5 HRS	
			20W-50. Lube engine controls.		
ROUGI	HT FORWA	RD			
MODO:	TOTALS				