

27



# ***TIFFIN AIRE INC.***

**3861 Co. Rd. 140  
Findlay, Ohio 45840  
1-800-553-7767  
Fax 419-299-3244**

**Propeller Log Book**

Stack  
Owner Name

Shettel Aviation

Address

Business Airport of Carlisle, Petersburg Rd.  
Carlisle, Pa 17013

Propeller Make

Hartzell

Propeller Model

HC-E2YR-2 RBSF

Blade Model

F8465B-7R

Hub Serial No.

BP 7590

Blade Serial No. 1

C44226

2

D41242

3

—

4

—

## PITCH RANGE

High

20.4°

Low

15.2-14.5°

Feather

79.7°

Reverse

Maximum Hours or Service Life between overhaul required by Mfg.

2000

Hrs. or

5

years interval between overhauls.

# SERVICEABLE

PROPELLER UNIT MCCAULEY  
MAKE

HC-E2YR-2RBSF BP 7590  
MODEL SERIAL NUMBER

The component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.

Pertinent details of the repair are on file at this repair station under:

*STOCK*

OWNER SHETTEL AVIATION

WORK ORDER NO. 13110

DATE 05/30/97

*[Signature]*  
SIGNED FOR

Tiffin Aire Inc.  
3861 Country Road 140  
Findlay, Ohio 45840  
419-299-3562  
800-553-7767  
FAX 419-299-3244

F.A.A. Repair Station Number IC5R930M

Work Performed by \_\_\_\_\_  
Repair Station #IC5R930M. Work Order/Invoice # \_\_\_\_\_

\_\_\_\_\_  
Signatures  
and Station  
Numbers

# MAINTENANCE & SERVICE HISTORY

Signatures  
and Station  
Numbers

Date 05/30/97

Propeller Total Time UNKNOWN

Tach/Hobbs Time UNKNOWN

Propeller Time Since Overhaul -0-

COMPLETELY OVERHAULED PROPELLER ASSEMBLY IN ACCORDANCE WITH HARTZELL SERVICE MANUAL #117D. STRAIGHTENED BOTH BLADES. SHOT PEENED (2) BEARING HUB SEATS. COMPLIED WITH SERVICE BULLETIN #213. COMPLIED WITH SERVICE LETTERS 177,61T,69,82A,101A,148A,154,155A.

COMPLIED WITH SERVICE BULLETINS 118D,136H,142B,159A,213,224R1,226R1.

COMPLIED WITH A.D. NOTES 71-21-09,77-12-08. END.

Work Performed By Tiffin Aire Inc.

Repair Station #IC5R900M. Work Order/invoice # 13110

Signature







# MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
4/2/99	1268.8 Hobbs	198.0 Hrs.	Serviced propeller w/ Aeroshell 6 grease. No leaks noted. I certify that this aircraft propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition. END	Cresoy J. Shaw AIP 282744266 IT.
2/1/00	1472.6	A/C Hobbs	C/W Annual Inspection Greased & Lubed	Reproduction ATR 135X

J&J Aviation Inc.  
2900 Bobmeyer Road  
Hamilton, Ohio 45015

Hartzell

Date 3-28-2001

N600MP

HC-E2YR-2RBSF

SN: BP7590

SPOH: 620.2 Hrs

Hobbs 1691.0 Hrs

Right Prop

Completed an Annual Inspection of this aircraft propeller on this date. Greased prop with Aeroshell #6 grease and serviced prop dome with nitrogen. I certify that this aircraft propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition. -END-

Jeffrey J Whyte  
Jeffrey J Whyte I.A. 297760788

