

TEXTRON Lycoming

ENGINE LOG

~~N9527W~~

SSP-1872-1

S

TEXTRON Lycoming

652 Oliver Street
Williamsport, PA 17701 U.S.A.
570/323-6181

ENGINE SERIAL NUMBER

R	L	-	1	2	0	0	3	-	3	6	A
---	---	---	---	---	---	---	---	---	---	---	---

IN SERVICE DATE

0	6	2	4	0	1
---	---	---	---	---	---

 ENG.

--	--

 T.T.

		0	0
--	--	---	---

DETACH AND RETAIN THIS PORTION FOR YOUR RECORD

TEXTRON Lycoming

652 Oliver Street
Williamsport, PA 17701 U.S.A.
570/323-6181

ENGINE LOG AND MAINTENANCE RECORD

RECORD OF TEXTRON LYCOMING 0-320-D36 RL-12003-39A
MAKE MODEL SERIAL

FROM _____ 19____ TO _____ 19____
DETAILING TIME FROM _____ TO _____
HOURS HOURS

SSP 1872-1

© 1994 by Textron Lycoming "All Rights Reserved"

October 1994

TEXTRON Lycoming

652 Oliver Street
Williamsport, PA 17701 U.S.A.

TLRED-489
(Rev. 10-96)

This engine has been overhauled/rebuilt in accordance with the applicable Textron Lycoming manuals. All applicable Federal Aviation Administration Airworthiness Directives and Textron Lycoming Service Bulletins have been complied with. All parts have been inspected and have been determined airworthy to return to service. All accessories as part of the type certificate are either new or newly overhauled. Refer to enclosed Form ET001 for applicable accessory part numbers and serial numbers.

Engine Model:

Serial #:

Total Time:

Work Order #:

Date Completed:

O-320-D3G

RL-12003-39A

0.0

GJ159903

5/3/01

Authorized Signature

Textron Lycoming

652 Oliver Street

Williamsport, PA 17701

Repair Station: EJ1R115K

Marque Dugan

ENGINE LOG

Serial No. _____

E.M.C. AVIATION SERVICES


351 AIRPORT ROAD
NOVATO, CA. 94945
(415) 892-9234 fax (415) 892-7544

"N" N9527W DATE : 06/24/2001 **MAKE/M:** LYC. O-320-D3G **SERIAL:** RL-12003-~~36A~~
37A
TACH: 4102.6 **TOTAL:** 0.0

THE FOLLOWING WORK PERFORMED:

INSTALLED FACTORY REMAN LYCOMING ENGINE MODEL O-320-D3G S/N RL-12003-36A
IN ACCORDANCE WITH STC # SA413CH. SEE 337 FORM FILED. INSTALLED ENGINE USING
NEW LORD MOUNTS, OIL COOLER, AND RUBBER HOSE KIT. ORIGINAL PROPELLER,
ALTERNATOR, AND PRIMER SYSTEM WERE INSTALLED. SERVICED ENGINE WITH 8 QUARTS
AEROSHELL 100 MINERAL OIL. GROUND RUN GOOD, NO LEAKS NOTED.

Signature

Certificate # 572578187 A&P

Page Total

Brought Forward

Total to Date

All Repair Data Must Bear the Endorsement of a
Certificated Mechanic, and his Rating and
Certificate Number MUST be Shown.

